

Landscape Consulting & Contract Management

"Protecting Your Landscape Investment"

925 Florida Avenue, Suite D Palm Harbor, Florida 34683

DRAINAGE SYSTEM MAINTENANCE INSPECTION REPORT

Date: May 28, 2020 Inspection # 5

Client: EAST LAKE WOODLANDS COMMUNITY ASSOCIATION

Attended by: Drainage Committee-Jack Picker, Jeff Fosbrook

AMI-Cary Williams Manager- Debi Hudrlik PSA-Tom Picciano

SCOPE

This was the fifth of the regularly scheduled maintenance inspections of the stormwater drainage system. During these reviews we inspect for issues that may adversely affect the flow of drainage water through the system. Items such as debris or silt build up in culverts, erosion, excessive vegetation, blocked drainage grates, and any pond control structures that may need maintenance shall be noted and prices for those corrective actions shall be provided.

FOR AMI RECYCLING:

1) Woodlands Parkway at Cypress Estates- clear vegetation and silt out of mouth of culverts. \$1,200.00_



Initial	Date
Initial	Date
Initial	Date

2) Woodlands Parkway- there are several locations where concrete flumes need to be constructed. They are marked with orange paint. Price per flume. **§ 2,695.00**



•	n	nr	A	ed	•
Γ	.vi	U	υv	ιu	,

Initial	Date
Initial	Date
Initial	Date

3) Woodlands Parkway inbound between Cypress Estates and Woodlake Wynde- clear vegetation and silt away from headwall. **§ 1,125.00**_____



Initial	_ Date
Initial	_ Date
[nitia]	Date

4) Woodlands Parkway outbound east of Woodland Estates at golf course #1 south- clear silt and vegetation away from headwall and out of ditch 100' feet in each direction. \$ 2,000.00



Initial _____ Date ____

Initial _____ Date ____

Initial _____ Date ____

5) Woodlands Parkway at office building- clear silt away from pipe that drains the parking lot. \$ 450.00



Approved:

Initial _____ Date _____

Initial _____ Date ____

6) Corner of Woodlands Parkway at East Lake Woodlands Parkway- clear silt from end of concrete flume. \$_450.00_



Initial	Date

Initial _____ Date ____

Initial Date____

7) Corner of Woodlands Parkway at East Lake Woodlands Parkway- eliminate the grass flume by re-grading. \$ 950.00



Approved:

Initial	Date	
---------	------	--

Initial _____ Date ____

8) East Lake Woodlands Parkway inbound across from office building driveway- clear vegetation and silt in area where multiple pipes empty. **\$ 2,300.00**



A	nr	r	77	'n
	IJΙ	,, ,	,,,	·u

Initial	Date	
Initial	Date	
Initial	Date	

9) East Lake Woodlands Parkway inbound along golf course- there are several locations where concrete flumes need to be constructed. They are marked with orange paint. There is also a larger eroded area which will need a flume as well as rip-rap and sod.

Price for standard flume \$_2,695.00

Price for larger eroded area with flume \$_5,600.00_



Initial	Date	
Initial	Date	
Initial	Date	

10) Woodlands Boulevard inbound and outbound west of Deerpath by "Caution Speed Wave Ahead" sign- clear vegetation and silt away from headwalls. \$\sum_{5,800.00}\$ * Needs to be Jetted - per AMI



A	nr	ri) II	PΛ	
	νL	,, ,	,,,	cu	•

Initial	Date
Initial	Date
Initial	Date
Initial	Date

11) Woodlands Boulevard Bridge at Isleworth- clean silt from creek and install rip rap by exposed pipe to prevent erosion and jet drains in ditch. \$3,500.00 Jetting and silt removal COMPLETED. Install rip rap \$1,250.00



Initial	Date
Initial	Date
Initial	Date

12) Woodlands Boulevard at Stonebriar- jet drains in ditch \$3,200.00 Provide price to replaced rusted grates. \$998.00



Approved	
-----------------	--

Initial	Date

Initial _____ Date ____

Initial _____ Date ____

13) Woodlands Boulevard at "Lake Aberdeen"- dig channel to newly installed drain box. **§ TBD**



Approved:

Initial _____ Date ____

Initial _____ Date ____

14) Woodlands Boulevard at Cross Creek- repair multiple pipe separations along pipe route. \$14,927.25 Per Section_

*Section consists of 20'



Approved:

Notes: Multiple dig sites, repairs to existing stormwater pipe will not exceed \$14,927.25 per section. Depending upon repair, new installation of pipe may not be needed which would lower costs depending on repair method used (i.e. poured concrete pipe collar or CMP repair band).

Initial	Date
Initial	Date
Initial	Date
	Road north of Woodlands Parkway- clear vegetation from channel EL between East Lake Road and Estates. \$24,672.00
Approved:	

Initial _____ Date ____

Initial _____ Date ____

PROPOSALS NEEDED:

EAST LAKE WOODLANDS COMMUNITY ASSOCIATION

16) Cypress Estates at Holly Hill- clear debris in front of headwall on entrance and exit side. \$_1,375.00



Initial	
Initial	Date
Initial	Date

FOR EAST LAKE WATER:

9) Nursery Rd-fabricate grate for wet well. Proposal requested by East Lake Water. **\$2400.00 NOT COMPLETED**



Initial	_ Date
Initial	_ Date
Initial	Date

FOR CLUB:

10) #1 North tee bridge to driving range at power easement- remove vegetation \$18,500.00 NOT COMPLETED



				-
A 1	nn	m	N 7 4	ed:
Δ	VU	,,,	,,,	٦u.

Initial	Date
---------	------

Initial _____ Date ____

Initial _____ Date ____

NEW 11) Maintenance path between #4 and #15 north. §





Approved:

Initial _____ Date ____

Initial _____ Date ____

12) Moccasin Creek along Tampa Rd-clear vegetation on both side of creek behind #15 south tee box. **\$22,850.00 NOT COMPLETED**



A	nı	nr	'n	VΑ	M,
	v	"	v	•	u

Initial	Date
Initial	Date
Initial	Date

13) Moccasin Creek along Tampa Road at #14 south green-needs to be bush hogged. **§650.00 NOT COMPLETED**



Initial	_ Date
Initial	
Initial	Date

14) #15 north/green/#16 north tee-assumed failure of drainage pipes underneath cart path structure. \$_____



Approved:

Initial	Date	
Initial	Date	-
Initial	Date	

- 15) General recommendation- the accumulated debris should be removed from control structures. Remove dead palm fronds from creeks on the golf courses.
- 16) East side of #4 north green-tree lying across the creek. **\$275.00 NOT COMPLETED**



Initial	Date	
Initial	Date	
Initial	Date	

17) Channel on #3 north fairway-repair creek bank, dead Bermudagrass. The Association previously seeded the bank and installed geo-textile fabric to hasten the seeding. Erosion will now cause sediment to spill into the creek until the bank is again stabilized. **\$9,500.00 NOT COMPLETED**

October 2018



Approved:	
Initial	_ Date
Initial	_ Date
Initial	Data

18) #1 north bridge to driving range at power easement-remove vegetation. **§18,500.00 NOT COMPLETED**



Approved:		
Initial	Date	_
Initial	Date	_
Initial	Date	

19) #1north bridge to fairway-repair weir. **§6,800.00 NOT COMPLETED**



						_	
•	n	n	14	ov	· ^	a	•
\boldsymbol{H}	U.	IJ.	L	Uν	C	u	•

Initial Date		
Initial Date		
Initial Date		
20a) #15 ^t south tee box	x from bridge	20b) #15 ^t south tee box from bridge
Remove low hanging t	tree limbs \$2,590.00	for both pictures NOT COMPLETED

October 2018 October 2018



Approved:		
Initial	_ Date	
Initial	_ Date	
Initial	Date	

21) Bridge at #4 north green-repair leaning wall and hole forming along cartpath. The wall behind the rip-rap is leaning, leaving a void between the two walls. Rainfall can get between the wall and rip-rap causing erosion. The hole along the edge of the cartpath is weakening the structural integrity of the path. **§42,000.00 NOT COMPLETED**



A	nn	rn	VA	ď
	սս	'I U	•	u

Initial _____ Date _____

Initial _____ Date ____

Initial _____ Date ____

FOR AQUATIC COMPANY:

22) Channel EL- aquatic weed control. \$_____



COST SUMMARY	
ELWCA Drainage System Maintenance	<u>\$</u>
Club Drainage System Projects	<u>\$</u>
East Lake Water System Projects	<u>\$</u>
Aquatic Company System Project	<u>\$</u>

ITEMS TO REMEMBER:

Repair of the drainage box on South Woodlands Drive.

Repair of joints and alternatively, replacement of 36" pipe through Cluster Four.

CLUBCORP RESPONSIBILITY- ITEMS TO REMEMBER:

Cluster 5- Phase 1 Control structure, grate, baffle. \$9,395.00 per estimate #323 dated 3/7/2019- placed on hold. Cost could be more if control structure needs repairing.

Cluster 5- Phase 2- Exploratory Excavation for Possible Pipe Collar. \$7,900.00 per estimate #323 dated 3/7/2019-placed on hold. Repair costs could be more based on findings.

Weir on pond #55- \$5,575.00 per estimate dated 1/15/2019.

SUMMARY

There were no large-scale repairs noted during this inspection. Most of the corrective actions involved the removal of silt and vegetation to improve water flow. In addition, several locations were identified for the installation of concrete flumes to quickly remove water from arterial roads and to help preserve the integrity of the asphalt. The concrete flumes would not require the same degree of maintenance as the grass flumes currently do.

Respectfully submitted,

Tom Picciano

PSA Horticultural