

PORT TOWNSEND REBUILD GROUP – Image Gallery (Sample)



From top left to bottom right: (1) Waves battering the exterior of the Hastings Building; (2) Dilapidated dock adjoining the Hastings Building; (3) Flooding in the basement of the Customs House; (4) Exterior wall damage to the Customs House facing Port Townsend Bay; (5) Hastings Landing dock in unsafe and degraded condition; (5) Exterior wear and tear on the Uptown Theater.