

Landscape Consulting & Contract Management "Protecting Your Landscape Investment"

8431 Prestwick Place Trinity, FL 34655

DRAINAGE SYSTEM MAINTENANCE INSPECTION REPORT

Date: December 14, 2022

Client: EAST LAKE WOODLANDS COMMUNITY ASSOCIATION

Attended by: Drainage Committee-Steve White

ELWCA-Mary McCoy

Club Corp-Andy Bianchi, Rick Bishop

AMI- Cary Williams

Manager- Monica D'Ambrosio

PSA- Tom Picciano

SCOPE

This was a regularly scheduled maintenance inspection of the stormwater drainage system. During these reviews we inspect for issues that may adversely affect the flow of drainage water through the system. Items such as debris or silt build up in culverts, erosion, excessive vegetation, blocked drainage grates, and any pond control structures that may need maintenance shall be noted and prices for those corrective actions shall be provided.

FOR MASTER ASSOCIATION /AMI RECYCLING:

1CA NEW South Woodlands Drive at pump station pond-water appears to be undermining road and sidewalk. Concrete gutter is sinking and sidewalk has noticeable pitch. \$



TO COMPANY OF THE OWNER OWNER OF THE OWNER OW		
Approved:		
Initial	Date	
Initial	Date	

InitialDate
2CA NEW South Woodlands Drive at pump station pond-remove large tree from water. \$
Approved: InitialDate
InitialDate
InitialDate
3CA NEW Sunflower pond at Greenhaven across from Greenhaven Circle-rip rap needs to be reset and pond needs to be dredged. Remove debris. \$
Approved: InitialDate
InitialDate
InitialDate
4CA NEW Sunflower at ballfield-provide multiple solutions (if possible) for compromised drainage culvert across from ballfield. \$
Approved: InitialDate
InitialDate
InitialDate

FOR LIBE	RTY LANDSCAPING:
1LL NEW I	Lakeshore Vista-fill in holes along sidewalk. \$ THIS HAS BEEN COMPLETED Date
Initial	Date
Initial	Date
FOR SUB A	ASSOCIATIONS:
	ore Vista- South Woodlands behind Lakeshore Vista wall-provide exploratory price to check on d operation of existing pipe. Pipe under the wall is compromised. \$
Approved:	
Initial	Date
Initial	Date
Initial	Date
FOR CLUE	S CORP:
	Bridge and cart path at Clubhouse-both have been undermined by water intrusion. \$
Approved:	Doto
1111tlat	Date
Initial	Date
Initial	Date
2CC NEW	Drainage box along cart path at Silverthorn pond-soil on the right side of box is eroding. \$



Approved:	
Initial	Date
Initial	Date
Initial	Date
	reek between Preserve and Cross Creek-bare sections of the bank should be seeded to prevent erosion. It to be moved to prevent vehicles from entering creek. Boulder is sliding down toward creek.
Approved: Initial	Date
Initial	Date
Initial	Date
4CC NEW N	ursery Road-grate is missing. \$
Approved: Initial	Date
Initial	Date

5CC NEW Nursery Road-right side of head wall is eroding. Rip rap is needed. \$______



Approved:

Initial _____Date ____

Initial _____Date ____

Initial _____Date ____

6CC NEW 365 Holly Hill-debris needs to be removed from grate. \$_____



Approved:

Initial _____Date ____

Initial _____Date ____

Initial Date

7CC NEW 10th green south course-erosion at drainage sump. Rip rap is needed. \$



Approved: Initial	Date
Initial	Date
Initial	Date

8CC NEW 11th fairway south course-mitered end of pipe is not stable. It has disconnected from pipe. Pond bank is eroding. \$_____



Approved:
Initial _____Date _____

Initial _____Date _____

Initial _____Date ___



December 2022



Approved:			
Initial			
Initial			
COST SUMM	ΔRV		
COST BUILDI	<u>AIVI</u>		
ELWCA Draii	nage System	\$	_
Maintananaa I	Shouty I andgooning	\$	
Maintenance 1	Liberty Landscaping	<u> </u>	=
Club Corp.		\$	_
_			
Respectfully su	hmitted		
Respectivity su	omitted,		
Tom Picciano			
PSA Horticultu	ral		
rsa noruculu	141		