



IMPORTANT INFORMATION BEFORE INSTALLING TURBOCHARGER

Nissan Patrol ZD30 Turbocharger

Model: Garrett GT2052V

Part No. 724639-5006S

Part No. 769328-5001S

PLEASE READ THE FOLLOWING INSTRUCTIONS CAREFULLY BEFORE INSTALLING THIS NEW TURBOCHARGER

Please understand why you are replacing the turbocharger before installing this new one.

Are you replacing the turbocharger due to failure or engine rebuild?

There are various items that require checking for correct operation and or replacement at this time. Any of these can be attributed to the cause of the original turbocharger failure, and consequently could cause the new turbocharger to fail.

Some common issues that may cause a failure, but are not limited to that which require checking:

- Check for fault codes
- EGR valve / solenoid operation
- Boost control solenoid valve
- Vacuum pump operation
- Air mass sensor
- Air intake pipework and air filter
- In the case of rebuilding the engine, ensure that a new engine oil cooler is fitted at this time.

Further research may be necessary to check for other components or faults.

By fitting this new turbocharger you have acknowledged reading and understanding the above. In the advent of the new turbocharger failing, BDG will forward it to the Manufacturer/Supplier (Honeywell Garrett) for the warranty inspection and report.

The Manufacturers decision with regards to warranty claims and associated costs will be final.