

Sample RSA: Arizona Tribal Road Safety Assessments







Tribal RSA Virtual Workshop

Kerry Wilcoxon and Jay Gomes – ADOT Steven Johnson – GRIC



Agenda

- RSA Process in Arizona
- Example Tribal RSAs
 - SR-87 at Gilbert Rd Gila River Indian Community
 - SR-389 MP14-30 Kaibab Band of Paiute Indians



2020 Traffic Fatalities*



1054 Deaths

8% Higher than 2019

239 Pedestrian



653 Lane Departure




284 Intersection Fatalities 1



3098 Serious Injuries

*as of 11/2/21








Arizona RSA Requirements


- Selection
- Owner
- Data
- Solution Oriented





Selection

- Network Screening or Agency Request
- Every request is honored
 - All requests receive either an external or internal RSA
 - External consultant
 - Internal ADOT staff
 - Ranking based on crash history
 - Timing based on resources




ADOT	agement and Operation	Non-sign		Traffic Sale Network ! ctions (Exc) Ho	sty Section	90		way Sys	Aem								
Network:	State Highway Syn	100	Period:	2015-2019					Qui	ry Date	1652121						
							Severity				1						
Street F.	Street 2	Treffic Control	ADOT District	DPS District	SHINIA Region	Abor Traffic Region	K.A. Total	(4)	Serious (A)	Poss (BK)	PDO (0)	Total Creshes	Primary Futal/Serious Craels Type	2018 Rmk	2019 Rank	2020 Rank	Continues
139-99	Flerco Ferry Rid		Northwest	Dissolt 1	:A3:	Northern	33	5.1	3.0	- 11	327	56	Angle	10	.2	11	Plans are in place to makin the left turn lates an current coestuction project
SRAT	SR 287 Spelli Rd	2 way stre	Southernal	Dissist 6	A-1	Southern		3	5	6.	10.	76	Anglo		. 9	5	Internal HSA in 2029, Implemented signing and striping countermeasures in 2029, RTE. requesting HSEP project modification to include SD RT Easy 7 (3)57.
SRI &7 (Final: County)	Gillien Fid Strennic Rd	2 www.itiap	Solicetel	District 6	At	Southern	.7	2	8	8	24	51	Aright			3	HSP Signalization FY 19-20, Traffic Signal activated 12-0-2029
SR-347	Maricepa Commed Fet	rash areas areas		Molio Certral		Central	-6	2	4	8	27	36.	Lift tiers	1	7	4	RSA May 2016 Signal is warranted & design this year
105 Art Count No.			Cornel		14	Compl		- 1	- 5	5	12	78	Nones	107	NIT	hitt	RSA Graft in program (MP 4.85 SR)
							- 5	- 6	-		27	132	Angle	100	Mil	161	PSA Cod in programs (AP 100 C) Internal PSA fall 2018. Implemental slipping and musking coordermateured in sammer 2
381-05	Thisseless (Nd.	Div'1-way step		Metry West	A.1	Compl	14	3	2	11	0.1	33	Angle	NR.	25	2	(MP 161)
521-60	Thompses Avo.	Div 2-way step	Nurthwest			Northern		- 21	-4	5	17	- 50	Angle	. net	.14	74.	RISA Draft in progress (MP 68 3)
10/04	Page Springs Rd				141	Maryeri	4	X	1	4	141	168	New	RR	HR	54	Signing and marking improvements over histalled in January 2020 after PSA was sumpleted in 21th IMEP Project for interaction Improvements to Install LT lanes with profiles offset (Solder landing line for PYZ)241. Confines Mechanising (MP) 502-51.
TR49	Spring Ln-	Div I -only ship	Northwest:		43	Vuithert:	- 4	2	- 2	-3	-	13	Angle	23.			A traffic signal is currently under design for construction in FY 31.
	1980 April			Mehro Villed							- 36		Angle	MR.	hil.	167	PCA (nath in progress (MF 150 S)
		Tiv 2-way Mag			3.4	Campai	. 3			1	16	76	Angle	NR.	161	hir	
50.85	Broadway Flat	Div 2 way into		Makin West	163	Demai	X	2	1	12	- 1	124	Angle	1	*	8	Internal PSA fall 2019, implemented signing and marking counterweasures in sammer J (667-15.3)
13.65		2-way does				Comman	- 2	- 0	1		_		Anidio	RH	164		
5R-74	Now Fitter Fid	1-way stop	Cerylaud	Matro West		Control	- 3		-1-	- 3	- 6	12	None	MR		NR:	
SR-67 SR-60	Bartlett Ho Franchic	2-way stop.	Southeaster	Cintrict 6	A-1	Southern		2	-	100		9	Angle Left hare	AR	18	12	(MP 130.4) internal RSA performed 4/2526, Countermeasures installed 8/2526
58.90	Cooperative Way	Div 2-way stop	TO STEWARD	Dispired 5	A-3	Southern	-2-1				-			NR.	NR.	NR.	TESA field revises done March 2021 TESA Draft in progress ARP 251 21
580.00 584.07	S&L107	Party state		Detor 6	A-1			-	-	21	-	3	Angle Angle	MI	MR	Mil	FOR two review come tearth 2021 FCM chart in progress (for 2012) F0156 - Signal activated 12/2/2020
58.65	Walley Woor (V	2-way stop	Northeast.	Dignit 12	A-3	Northern		3	-5	1	74	100	Tetter	1	1 4	15	RISA Disaff in programs (MP 2019 1)
58.00	Suppossible River	2 way step	Control	Displot H	A-4	Curtical	3	-	7		33	10	Angle	10	19	NR	
5H-268	Has Mana Tri	1-way stop-	Northcontal	District 12	A-1	Nuctiver		4.1	-2	. 4	20	31	Angle	NR	- 14		RSA Druit in progress (MP 207 2)
US-600/Apecha Tri	Mountain Rd	Oly 2-arity step		Water East	.A4	Central				- 8	20	30	Angle	AH	104	NH.	HSA stone in 2014 (USSEX - Sensionary Rd to Monday Rd)
1/5-85	orth Lake Power El	2-way strip	Northcontral	District.2	A-1	Northern	2	-2.	.0	6	18.	76	Lotter	MR	NR	161	
US-60/Grand Ave	Morele Vista Rd	Div Zway stop	Central	Metro West	A-4	Central	2	.0	-2	. 2	10	- 25	Left turn	101	161	101	RSA Diet in progress (MF 161 25)
													ASS - Did not a		201520	13/2020	tog



Owner


- Agency contact for history and follow up
- Usually submits request
- Relays concerns
- Responds to RSA findings





Data

- Process is data-driven
- Must have some form of measurable safety condition
 - Crashes
 - Speeds or documented bad behavior
- Before and after results tracked



TRAFFIC UNITS #1 AND #2 WERE BOTH TRAVELING EASTBOUND ON SR 260 NEAR MILEPOST 262.5. A PARTIAL ROLL OF WIRE FENCING FELL FROM THE BED OF TRAFFIC UNIT #1 INTO THE ROADWAY. TRAFFIC UNIT #2 WAS TRAVELING BEHIND UNIT #1 AND STRUCK THE WIRE FENCING; RESULTING IN MINOR CONTACT DAMAGE TO THE PAINTED FRONT BUMPER. BOTH DRIVERS DENIED SUSTAINING ANY INJURES. BOTH VEHICLES WERE DRIVABLE.



Solution Oriented

- RSAs performed to:
 - Investigate problem
 - Develop solutions
 - Recommend countermeasures
 - Reduce crashes and Save lives
- RSAs are not intended to address feelings
 - Road "feels" unsafe





Scheduling an RSA in Arizona

Contact:

Arizona Department of Transportation RSA Program

Web page:

https://azdot.gov/business/transportation-systemsmanagement-and-operations/operational-and-trafficsafety/road-safety

Email:

AZRSA@azdot.gov

Phone: RSA Program Manager: 602-712-2332





Tribal RSAs Examples

SR-389 MP 14-30

Kaibab Band of Paiute Indians

SR-87 and Gilbert Rd


Gila River Indian Community





SR-87 and Gilbert Rd

- Un-signalized intersection
- SR-87 bi-pass for I-10
 - Rural two lane state route
 - Speed Limit 65 MPH
- Gilbert Rd
 - Rural two lane tribal route
 - Speed limit 55 MPH





SR-87 and Gilbert Rd

- Primary Crash/Violations:
 - Angle and left turn
 - Failure-to-Yield



- Overall safety, limited visibility for Gilbert Road traffic
- Location ranked first on statewide network screening



ADOT

SR-87 and Gilbert Rd

Results of Site Visit

- Previous Safety Projects
- GRIC turn lane installation
- Increase in Commuter traffic
- Decrease in gaps, high speeds
- Increased need for lighting in the area



ADOT

SR-87 and Gilbert Rd

Recommendations

 Perform Traffic Signal Analysis




- Provide Intersection Lighting
- Provide Community awareness

SR-87 and Gilbert Rd

Outcome

- Signal warrants met
- State applied for safety funding through Highway Safety Improvement Program (HSIP)
- Signal installed 2019





Rural two lane state route

- Speed limit: 65 MPH
- Volume: 1900-2300 ADT
- No or inadequate turn lanes
- Concerns for turning traffic safety
 - Especially at Pipe Spring Nat. Mon. Rd



ARIZONA ROAD SAFETY ASSESSMENT APPLICATION

- Name, Position/Litte, Address of Contact Person: Laura Savala, Council Member HC 65 Box 2, Fredonia, Az. 86022
 - Manuel M. Sevala, Chairperson Manuel M. Sevala & Chairperson MSevala & Chairmers & Cha
- Type of assessment requested (planning, design, construction, existing): Existing
- 3. Specific location of proposed RSA project (intersection, spot location, road segment or project, or new facility);
 Rosse(s): SR389
 Segment: In Rathab Reservant largest: 16 miles RSA
 Fromfit of disegment/project): Mile Post 14 to 10
 Segment Length: 16 Wikes
 City/Comp/Tribe: Bohava County, Kathab Painte Indian Reservation
- Describe any improvement plans, including stage (scoping, design, construction, etc.), for this location None - all existing conditions
- 5. Reasons for requesting RSA:
 - What interested in turn lane improvements at CR240 County Road intersection. Other safety concerns/locations were identified in ADOT RSA By Mike Blankenship in 2009, site visit.
- What is the crish experience for the most recent 3-year period (total crishes, fatal crashes, injury crashes, crish rate, cic.)? (not applicable for new facility) __All_data_will be from ADCT's records.
- Does your agency have it method to identify and prioritize road safety issues? <u>NO</u> If yes, where does that location rank within your agency's problem locations?
- 8. Average Daily Traffic (ADT) volume for rond(s): up 49.19 to up 19.19 1960

 ADDT Counter ID# 101654
- Please list month and/or days of week when safety issues are most prevalent, if applicable flowday to Friday 8 am 5 pm
- 10. Describe any future development planned for this area:
- New Subway Restaurant at SR389 & CR 240 (Pipe Spring Rd.), and renovation of RV Campground.
- Please include any additional road owners, photos anc/or other information that highlight the location: Truck movements are difficult & create problems with sight distance. State Route
- 389, within the Kaibab Indian Renervacion; Mike Mishkenship did BSA at BiA Rt.50 [2 Signature (and printed mump) of Person with Authority to Respond To/Implement the RSA Findlags: In 2009, Nature J. N. Savala, Chairperson Date: 23 October 2013

Submit Application to:

Road Safety Assessment Program Manager 1615 West Jackson St., Mail Drup 065R Phoenix, AZ 85007-3217

Phone: 602-712-7601 Fax: 602-712-3243 Email: mblankenship@azdot.gov



- Crash History:
 - 31 crashes 2004-13
 - Severity:
 - 1 Serious Injury, 7 Non-serious injury, 4 possible injury
 - 19 property damage only
 - Primary Crash Type: Rear-End and Rollover
 - Primary Driver Violation: Speed-to-Fast





Community Concerns:

Intersection

- South Antelope Valley Rd
 - Lack of advanced signage
 - Mining Trucks
 - Drivers directly accessing SR-389 from shoulder





Community Concerns:

Intersection

- Pipe Spring National Monument Rd
 - Lack of turn lane storage space
 - Trucks parking on shoulder
 - Intersection not lighted
 - Shoulder drop off







Community Concerns:

Entire Route

- Signing understandable to international visitors
- Delayed emergency response times





RSA Field Observations

- Generally well maintained
- Adequate sight distance and shoulders
- Most of the community concerns validated incl.:
 - Turn lane length, parking and shoulder access
 - Some sign clutter





RSA Recommendations

Inter: Pipe Spring National Monument Rd


Lengthen right and left turn bay storage





Outcome

- RSA Report Published
- Tribal Transportation Program Safety Funds (TTPSF) applied for
- Pipe Springs turn bay extension project approved for funding 2017
- Funding amount: \$369,000
- Installed March 2020





RSA Overview

Roadway problem or concern reported Crash and roadway data reviewed RSA conducted

Recommendations should address:

Patterns? – Yes or No

Solutions? – Yes or No

Actionable? – Yes or No





Questions?