



Malfunctioning Pressure Relief cartridge due to debris. Pressure relief would open and close rapidly causing this scenario and the bed would not lift a bale. The solution was to force high flow ratings in pressure relief situations such as the rephase cycle.