

## Chevrolet and GMC Trucks (Diesel) Call 1-800-530-5624 for assistance with your application



	DURAN	MAX DIESE	L						
Truck		ENGINE Belt	Pump		Hose Set		Dash	HydraSTX	Adapter
Year	Liters	Туре	Mounting Kit	Pump	Extended/Crew Cab	Level-Lok	Bracket	Dash Match	Plug
82-85	6.2	٧	CMK614-2	RP6-11	HS146	<u>ULL-1</u>	<u>HX-01</u>	N/A	PL-U
Built Before Janu	iary 1, 1985								
85-89	6.2	VP	CMK624-2	RP6-11	HS146	ULL-1	<u>HX-01</u>	N/A	PL-U
Built After Januai	ry 1, 1985								
88-94	6.2, 6.5	S	CMK654-2	RP6-11	HS122 or HS146	CLL-2	HC-01	N/A	PL-U
95	6.5	S	CMK654-2	RP6-11	HS122 or HS146	CLL-2	HC-02	N/A	PL-U
96-00	6.5	S	CMK664-2	RP6-11	HS122 or HS146	CLL-2	HC-02	DB-C1-STX	PL-U
2001-2007 CL	6.6	S	CMK694-I6	RP6-11-6	HS122 or HS160	CLL-4	HC-03	DB-C1-STX	PL-C
2007-2010	6.6	S	CMK694-I6	RP6-11-6	HS122 or HS160	CLL-4	HC-04	DB-C2-STX	PL-C
2011-2014	6.6	S	CMK2604-I6	RP6-11-6	HS122 or HS180	CLL-6	HC-04	DB-C2-STX	PL-C
2015	6.6	S	CMK2604-I6	RP6-11-6	HS122 or HS180	CLL-6	HC-05	DB-C3-STX	PL-C + C
2016	6.6	S	CMK2604-I6	RP6-11-6	HS122 or HS180	CLL-6	HC-05	DB-C3-STX	PL-C + C
2017-2019	6.6	s	CMK261A-I6	SP4-11-45-6-A	HS122 or HS180	CLL-6	<u>HC-05</u>	DB-C3-STX	PL-C + C3
2020-2023	6.6	s	CMK263A-I6	SP4-11-45-6-A	HS122 or HS180	CLL-8	HC-06	DB-C4-STX	PL-C + C
2024 - Present	6.6	S	CMK263A-I6	SP4-11-45-6-A	HS146 or HS180	CLL-8	<u>HC-06</u>	DB-C5-STX	PL-C6
1989-2000 Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require						CLL-3			
2000-2006 Only									
2007 Newer Body Style Require								DB-C2-STX	
2001-Present Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require						CLL-5			
2020-Present Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require									PL-C + C
2019-Present 4500HD & 5500HD Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require  CMK262A-I6  CMK262A-I6						ULL-1			PL-C7
2001-2005 DIESE	L USED CMK68	4-6, if ch	anging to a CMK694-0	6, consult factor	у.				
2001 DIESEL Req	uires Belt 5061	380 due t	o O.E.M. Belt Routing	j.					
	his truck is equ	ipped wit	h K76 dual alternator		er's side alternator must be	removed and th	ne onboard cor	nputer reflashe	d by
				t make truck	new Level Loks will no	rmally be reg	uired.		
					= <b>0.0. =0.00</b> 110				