

Drainage CCTV Survey

Client Reference

Site Address

Job Details

Drainage Services - Pre-Purchase CCTV Drainage Survey & Report

Engineer Comments & Works Carried Out

Full CCTV survey carried on drain lines serving toilets, sinks, showers and baths. Both minor and major issues found in drain line.

Video Footage Attached Separately

Further Works



Recommendations



Immediate Issues



Further Works + Recommendations

Major pipe damage and pipe fissures found between approx 10-18 feet upstream from driveway manhole towards rear patio manhole. Drain line is currently flowing, however pipe damage will deteriorate further. Drain relining or replacement recommended.


Solidified cooking fat found inside drain line, high pressure jet service clean is recommended.

Drainage Map & Pictures Below




Site Report

Map





Site Report

Map



Site Report

CCTV Photos



Major pipe damage found between 10-18 feet upstream from driveway manhole. Repair required

Site Report

CCTV Photos



Settled cooking fat found in drain line. Service clean recommended