



CK106 DEVICE INSTALLATION

GPS SOLUTIONS OF AMERICA

PROCESS OF INSTALLATION

CKI06 QUICK REFERENCE GUIDE:

- Connect power Harness to Device.
- Red wire to constant 12 Volt power.
- Black wire to solid ground source.
- The label and LED side of device needs to face up and not covered by steel
- Attach the solid black side of the device of the surface where you are installing it.
- After placing device where you want it, on your account check for location accuracy before completing installation process.

➡ On the right-hand side is the LED light diagram for the GPS and Cellular network connectivity status.

GSM LED(Red)	NO SIM Card	Dark
	Searching the network	Fast flash
	Register network successfully	Slow flash
	Connect Server successfully	Solid
GPS LED(Blue)	Gps is locating	Fast flash
	Successful location Or Power on	Solid
	GPS turned off	Dark

When installing this device, this is the side that needs to face up.

