RAM
REGIONAL ASSET MAINTENANCE

(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT

1. Inspection Details

Wavepool Balance Tank

Darwin Wavepool

21/10/2025

09.00AM

Inspector Name: Daniel Finn

Contact Number: 0427 870 596

2. Inspection Overview

Visual Inspection

Number of Personnel on Site: 3

PPE Compliance: Yes

SWMS, JHA and CSE in Place: Yes


3. Observations & Findings

The overall condition of the tank was good. PVC piping is in good visual condition. 316 Stainless steel brackets are in good condition with signs of scaling built up and only minor signs of material corrosion. The concrete walls were in good overall condition with one area showing a small breakout approx. 30cm x 30cm. sand and silt was approx. 100mm – 150mm deep in places on the floor of the tank.

(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT

4. Diagram



4. Additional Notes

RAM recommend that the balance tank be inspected every 2 years to monitor condition of piping, bracketry and overall tank condition. Next inspection, the following areas would require effort.

- Remove all sand and silt with vac truck
- Addition of scaffold to further inspect bracketry, remove scaling and assess integrity, replace clamps/brackets as required.

RAM
REGIONAL ASSET MAINTENANCE

(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT

5. Photos



RAM
REGIONAL ASSET MAINTENANCE

(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT







(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT



RAM
REGIONAL ASSET MAINTENANCE


(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT



(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN


SITE INSPECTION REPORT



RAM
REGIONAL ASSET MAINTENANCE


(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT



(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT



(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT



(08) 8942 7222 |
sales@ramservices.com.au |
108 Pruen Road, Berrimah NT 0828 |
GPO Box 1973, Berrimah NT 0828 |
61 096 629 006 | ABN

SITE INSPECTION REPORT

