

NOTICE



Caution: Do not sit on the wall.

Wall will not support your weight causing loss of water!



The spa tub is made of soft and flexible PVC material and the amount of inflation air may cause the tub connection fittings to be offset slightly from the control base connection fittings.

This is normal!




If the connection fittings are not aligned, with the spa empty, do the following:

1. Locate the large connection pipe on the tub first, put one hand under the large pipe and lift the tub slightly until the large connection pipe is aligned with the control base large connection pipe.
2. Bring the tub closer to the control base so that the control base large pipe fits into the tub large pipe and then securely tighten the collar nut by hand.



3. The two small connection fittings on the control base are flexible. Slightly bend the control base lower small connection pipe in order to align it with the tub small connection fitting. Tighten the collar nut securely by hand. Repeat the process with the upper small connection pipe.



With time the spa tub may develop wrinkles around the top wall surface, this is normal!

To keep your spa tub in optimum condition and to minimize heat expansion, avoid setting up the spa under direct sunlight and cover the spa tub when not in use with the spa cover.