

Agenda - Sewer Board Meeting - August 2026

- 117 Cedar view. Customer complaint. Low vacuum due to leak caused the tank to not fire. Manually emptied tank.
- 139 Lynn Lane. Controller malfunctioned
- 108 Lynn Lane. Replaced fernco in tank
- 3155 Vanleer Hwy. Repaired Fernco in tank
- Luke Lane pump station. High level alarm. Replaced one of float cleaned filters on pumps
- 3411 Hwy 48 . Repaired fernco. Replaced Valve and controller
- 3155 Vanleer hwy Ferco repair
- 3411 hwy 48 N. replaced controller
- Charlotte Middle School. Debris hung under the valve. Manually opened tank cleared blockage
- 787 Spring street. Replaced controller
- 108 Lynn lane. Tank Full Replaced controller and valve
- 721 Spring street. The controller hung open.
- 3368 Hwy 48. Cleaned pump filter adjusted Floats
- 3055 Vanleer hwy replaced controller
- 106 Dunning St. Replaced valve and controller
- Line broke at the pharmacy During excavation of drainage ditch.
- 224 Park Circle. The Tank was full. Replaced valve and controller
- 108 Dunning street. Manually triggered valve to reseal
- Dickson County Jail. Replaced controller. Staying open to long
- 124 Corlew Street. Removed valve cleared plastic cut out blockage
- 3499 Hwy 47. Rewired floats to run one pump.. Cleaned filters on pumps. Waiting on floats to arrive from Adenus to.
- Rerouted service line from Johnas Pizza to keep it on the back side of the pharmacy's drainage ditch.
- 216 Park Circle West. Tank Full. Hose had split in it causing the controller and valve not to open properly. Replaced 5 ft of hose

- 3928 Hwy 47 Pump went out. The pump was replaced in May of 2026. Should be warrantied by Adenus technologies.

Sewer Taps

- 124 Corlew Street ready to be added to billing
- 108 Phillips Street ready to be added to billing
- Next tap will be the old jailers house next to the square

Trucks

- Truck 1 added thicker oil and oil additive. Oil consumption/leak has slowed down
- Truck 1. Had 2 no starts. The motor turns over but will not start. No codes present when hooked up
- Ton dump truck. Replaced oil pressure sending unit and gasket. Slowed oil consumption.

Sewer Plant

- TDEC Inspection at Sewer plant was completed on 8-13-2026
- Have not received any updates if there are issues or concerns.