

Bull Shoals wastewater monthly report

May 2026

- Called out to sewer back up on Carolyn drive, had to call out mountain Home jetter. Sent down sewer camera 75% still clogged with roots.
- Reinspected smoke test defects,
- Replaced section of 8" sewer main on Carolyn Drive due to root infiltration and section of 4" service line.
- Jack Tyler Tech installed mini-cas and reprogrammed pump for drying bed lift station. (no charge)
- Filed CIP with ADEQ
- SEFC provided new software for tracking smoke testing results
- Received training and certification for use of bucket truck
- Reinstalled microstrainer that went to Iowa for repairs
- Assisted with 2 water leaks
 - Redbud Ave and Lynette Ave
 - 600 block of Carolyn Ave
- General daily plant checks and maintenance.
- General facilities housekeeping.
- Continued locating and GPS'ing of Sewer Manholes to build a GNSS/GIS asset management program for city 's infrastructure.
- Lift station inspections and general maintenance.
- Take four-hour composite samples to send to Arkansas Test Labs.
- Treated 4,841,000 gallons in April.

Michael Salentine

Wastewater Supervisor