




4 CHEVROLET 1958



HL-15




HL-15F




RFP-48B

HL-15 HEADLIGHT PANEL,top
HL-15F HEADLIGHT PANEL,front
RFP-48B REAR FENDER PANEL,Impala


1959




RFP-45



QPFS-26



RFP-45BX





RP-69C

RP-69CE


RP-69AC

RP-69C 2-dr ROCKER
RP-69CE 2-dr ROCKER,extended
RP-69AC 4-dr ROCKER
QPFS-26 QUARTER PANEL FRONT SECTION,also ElCamino
RFP-45 FENDER PANEL,except Stationwagon
RFP-45BX FENDER PANEL,lower rear-except Stationwagon

1960




RFP-52



QPFS-28



RFP-52BX



RP-69C

RP-69CE

RP-69AC

RP-69C 2-dr ROCKER
RP-69CE 2-dr ROCKER,extended
RP-69AC 4-dr ROCKER
QPFS-28 QUARTER PANEL FRONT SECTION,also ElCamino
RFP-52 FENDER PANEL,except Stationwagon
RFP-52BX FENDER PANEL,lower rear-except Stationwagon

#TOO LARGE FOR UPS