Sun Steel Treating

SPECIFIC LOTO INSTRUCTIONS

Company Name

Equipment ID:	Vacuum Furnace #32	Date Created:	3/28/22
Description:	2 Bar Vacuum Furnace	Person:	Andrew Smith
Facility:	Vacuum Building	Date Revised:	
Location:	Right Hand Side Front Vacuum Section	Person:	



2 Lockout Instructions Fo

Follow the lock out instructions below.

Any machine modifications must be shown in this procedure. Contact facility manager to update this procedure.

Always perform a machine stop before locking out disconnects.

Energy Source	Device used to De-energize	Location	Method	Try Out Check to Verify Equipment is De-energized Test Current Before Performing Work			
Electrical, Nitrogen	Main Breaker, Glass Blower Breaker	Right Hand side of furnace	Lock and Tag Main Breaker and Gas Blower Breaker, Open Door				
			i Call Anie				

#	SPECIAL INSTRUCTIONS									
1.										
2.			5 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	7. 1			1.			
3.									1 1 1 1 1	
	× 1						3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3		- 1 .	
		= =	110	, a-	1, 1, 1			==	 	
					Jil Qi					

Reference: Typical minimal lockout procedure – 29 CFR 1910.147 App. A

Enforcement: Failure to follow proper lockout-tag out procedures may result in disciplinary action up to and including termination.

