



# MAG-DRIVE PUMPS FOR CORROSIVE PROCESSES

CP-U0 - 3500RPM

GENERAL PERFORMANCE CURVES, REFERENCE ONLY

(English Units)

Pump: 1.5x1x5 Series: Chemag CP-U0 mag


S.G: 1.1 RPM: 3500




chemag.com

## PERFORMANCE


TRIM:	Max	1	2	3	4	Min
(in.)	6.13	5.50	5.00	4.50	4.00	3.25




## EFFICIENCY



## POWER



## NPSHr





# MAG-DRIVE PUMPS FOR CORROSIVE PROCESSES

CP-U1 - 3500RPM


GENERAL PERFORMANCE CURVES, REFERENCE ONLY  
(English Units)

Pump: 2x1.5x6      Series: CP-U1 mag  
S.G: 1.1            RPM: 3500




## PERFORMANCE


TRIM:	Max	1	2	3	4	Min
(in.)	6.13	5.50	5.00	4.50	4.00	3.25




## EFFICIENCY



## POWER



## NPSHr





# MAG-DRIVE PUMPS FOR CORROSIVE PROCESSES

CP-U4 - 3500RPM

**GENERAL PERFORMANCE CURVES, REFERENCE ONLY**

(U.S. Units)


**Pump:** 2.5x2x6    **Series:** CP-U4  
**S.G.:** 1.00        **RPM:** 3500




chemag.com

**PERFORMANCE**


TRIM:	Max	1	2	3	4	Min
(in.)	6.13	5.50	5.00	4.50	4.00	3.58



**EFFICIENCY**



**POWER**



**NPSHr**

