


Understanding the Signs

A visual warning system for icy conditions




FREEZING RISK ❄️

Temperature is at or below 32°F (0°C)

Ice presence likely

Use Caution - Follow procedures




NEAR FREEZING ❄️

Temperature is near 34°F (2°C)

Ice may be present

Use Caution



LOW RISK

Temperature is above 38°F (3°C)

Ice unlikely

WHAT TO DO WHEN YOU SEE BLUE?

Walk carefully and wear footwear with good traction

Use handrails and marked walkways

Allow extra time when entering or leaving the site

Report icy areas to your supervisor or facilities team



IceAlert signs are located at exits. Take a moment to notice the color before stepping outside

Pay extra attention when temperatures rise above and fall below freezing in the same day.