

檢測原因：DP-1200S 從 2008 年運轉至今，葉片轉子各零件是否有磨損？

檢測日期：2014.09.05 14:45

檢測樣品：2008 年生之 DP-1200S 樣品*1、2014 年生之 DP-1200S 樣品*1

批號	140531	080503
		
		

批號	140531	080503
上軸套		
上墊片	  	  

批號	140531	080503
葉片 磁鐵		
軸芯		

批號	140531	080503
下 墊片	  	  
下 軸套	—	此軸套卡在 pump 裡，無法取出

檢測結果：

DP-1200S 從 2008 年運轉至今，葉片轉子與全新的 DP-1200S 葉片轉子，各零件在尺寸上並無多大的差異，請見以上列表之照片比較，由此可知，京威 pump 之葉片轉子各零件，具有良好的耐磨性。



Yixuan
2014.09.05