



A 6 minute run time at 150 amps, would need a 31 minute cool time.

A 3 minute run time at 150 amps would need a 15 minute cool time. A 1 minute run time at 150 amps would need a 5 minute cool time.