



## Chevrolet and GMC Trucks (Diesel)

Call 1-800-530-5624 for assistance with your application



Truck Year	ENGINE Belt		Pump	Hose Set		Dash	HydraSTX	Adapter
	Liters	Type	Mounting Kit	Pump	Extended/Crew Cab	Level-Lok	Dash Match	Plug
Built Before January 1, 1985								
85-89	6.2	VP	<a href="#">CMK624-2</a>	RP6-11	HS146	<a href="#">ULL-1</a>	<a href="#">HX-01</a>	N/A <a href="#">PL-U</a>
Built After January 1, 1985								
88-94	6.2, 6.5	S	<a href="#">CMK654-2</a>	RP6-11	HS122 or <a href="#">HS146</a>	<a href="#">CLL-2</a>	<a href="#">HC-01</a>	N/A <a href="#">PL-U</a>
95	6.5	S	<a href="#">CMK654-2</a>	RP6-11	HS122 or <a href="#">HS146</a>	<a href="#">CLL-2</a>	<a href="#">HC-02</a>	N/A <a href="#">PL-U</a>
96-00	6.5	S	<a href="#">CMK664-2</a>	RP6-11	HS122 or <a href="#">HS146</a>	<a href="#">CLL-2</a>	<a href="#">HC-02</a>	<a href="#">DB-C1-STX</a> <a href="#">PL-U</a>
2001-2007 CL	6.6	S	<a href="#">CMK694-I6</a>	RP6-11-6	HS122 or <a href="#">HS160</a>	<a href="#">CLL-4</a>	<a href="#">HC-03</a>	<a href="#">DB-C1-STX</a> <a href="#">PL-C</a>
2007-2010	6.6	S	<a href="#">CMK694-I6</a>	RP6-11-6	HS122 or <a href="#">HS160</a>	<a href="#">CLL-4</a>	<a href="#">HC-04</a>	<a href="#">DB-C2-STX</a> <a href="#">PL-C</a>
2011-2014	6.6	S	<a href="#">CMK2604-I6</a>	RP6-11-6	HS122 or <a href="#">HS180</a>	<a href="#">CLL-6</a>	<a href="#">HC-04</a>	<a href="#">DB-C2-STX</a> <a href="#">PL-C</a>
2015	6.6	S	<a href="#">CMK2604-I6</a>	RP6-11-6	HS122 or <a href="#">HS180</a>	<a href="#">CLL-6</a>	<a href="#">HC-05</a>	<a href="#">DB-C3-STX</a> <a href="#">PL-C + C2</a>
2016	6.6	S	<a href="#">CMK2604-I6</a>	RP6-11-6	HS122 or <a href="#">HS180</a>	<a href="#">CLL-6</a>	<a href="#">HC-05</a>	<a href="#">DB-C3-STX</a> <a href="#">PL-C + C3</a>
2017-2019	6.6	S	<a href="#">CMK261A-I6</a>	SP4-11-45-6-A	HS122 or <a href="#">HS180</a>	<a href="#">CLL-6</a>	<a href="#">HC-05</a>	<a href="#">DB-C3-STX</a> <a href="#">PL-C + C3</a>
2020-2023	6.6	S	<a href="#">CMK263A-I6</a>	SP4-11-45-6-A	HS122 or <a href="#">HS180</a>	<a href="#">CLL-8</a>	<a href="#">HC-06</a>	<a href="#">DB-C4-STX</a> <a href="#">PL-C + C4</a>
2024 - Present	6.6	S	<a href="#">CMK263A-I6</a>	SP4-11-45-6-A	HS146 or <a href="#">HS180</a>	<a href="#">CLL-8</a>	<a href="#">HC-06</a>	<a href="#">DB-C5-STX</a> <a href="#">PL-C6</a>
1989-2000 Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require						<a href="#">CLL-3</a>		
2000-2006 Only								
2007 Newer Body Style Require							<a href="#">DB-C2-STX</a>	
2001-Present Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require						<a href="#">CLL-5</a>		
2011-2014 Higher Trim Levels May Require							<a href="#">DB-C2-STX DENALI</a>	
2020-Present Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require								<a href="#">PL-C + C5</a>
2024 - Present Chevy/GMC 40" & 56" C-A with Uplevel Lamps (Separated stop/turn)								<a href="#">PL-C6-SBT</a>
2019-Present 4500HD & 5500HD Dual Wheel Cab/Chassis (60" & 84" Cab to Axle) Applications Require			<a href="#">CMK262A-I6</a>			<a href="#">ULL-1</a>		<a href="#">PL-C7</a>
2001-2005 DIESEL USED <a href="#">CMK684-6</a> , if changing to a <a href="#">CMK694-6</a> , consult factory.								
2001 DIESEL Requires Belt 5061380 due to O.E.M. Belt Routing.								
2001-Present If this truck is equipped with K76 dual alternator option, the driver's side alternator must be removed and the onboard computer reflashed by authorized GM dealer to "single alternator" configuration.								
2024 - Present GMC "Denali" Package							<a href="#">DB-C5-DENALI-STX</a>	
2024 - Present GMC "Work Truck" Package							<a href="#">DB-C4-STX</a>	
<b>General Note: When switching any bed to a different make truck, new Level Loks will normally be required.</b>								