



Important

Please replace the three allen socket head cap screws used in mounting the clutch plate with socket button head cap screws 5/16-18 x 1 provided. This will provide adequate clearance between coil and plate on all assemblies. The clutch plate is shown below on item #3.



January 15, 2014