

cvi42®

Windows Quick Keys

cvi42 Platform

BASICS

Pan	←↑↓→ drag
Zoom	←↑↓→ + + drag
Undo	+
Redo	+
Delete Selected	←→
Copy Selected	+
Copy All	+
Paste	+
Hide All	shift

Play Cine

space

Refresh Study List

F5

Add to Case Review

+

Contours

ON/OFF

+ +

Scroll Through Phases

+ scroll

Fullscreen

F11

Preferences

F12

View All Images in Multi-View

M

Go to Next/Previous Series

/

Save Single Image as DICOM SC

F2

Save All Frames as DICOM SC

F3

WINDOW

Windowing

←↑↓→ drag or
 + ←↑↓→ drag

Auto adjust

← double click

Default

+

Presets

1 - 9, 0

ANNOTATION TOOLS

Line Contour

E

Freehand Contour

F

Annotation Text

T

Annotation Arrow

U

DELETE

Delete All	+ ←→
Delete All (Slice)	+ M
Delete All (Phase)	+ P
Cut Selected	+ X
Delete Selected (Slice)	+ D
Delete Selected (Phase)	+ O

FORWARD

Forward All	+ E
Forward Selected	+ F
Select and Jump to Next	tab

MOVE

Drag	+ ←↑↓→ drag
Push	+ ←↑↓→ drag
Reposition All	+ ←↑↓→ drag

EDIT

Smooth	+ S
Round	+ L
Refine	←↑↓→ hold
Click-Draw	+ ←↑↓→ click
Threshold Contour Definition	+ + ←↑↓→ drag

cvi42 | Web Viewer

BASICS

Zoom	 drag
Pan	 drag or  +  drag
Slice scrolling (coarse)	 drag
Slice scrolling (fine)	 scroll
Window/Level	 drag

Adjust phase

 drag
or  

Play cine

 at bottom
of viewport
or Press 

Rotate image

 +  drag

Maximize view

 double click

Next/previous series

On-screen arrow buttons  
or  / 

cvi42 | CORE CT

BASICS

Zoom	 drag
Pan	 drag or  +  drag
Window/Level	 drag
Scrolling through MPR	 drag
Rotate volume	 drag
Rotate MPR	 +  drag

Re-center MPR views/ Triangulate MPR views to the 3D view

 +  click
or  click

Maximize viewport

 double click

Context menu

 click

CMPR CONTOURS

Scale contour

 +  drag

Edit lumen/wall simultaneously

 +  drag

Delete centerline control point

 click

Quick Keys Valid for cvi42 v6.4