


Repair services



Renishaw repair services

Services offered

Repair

Your product is repaired to factory performance specifications, and carries a 3-month warranty.

Repair By Exchange (RBE)

Your product is replaced by a refurbished or as new product, shipped to you once we have received your failed product. RBEs carry a 6-month warranty.

Advance RBE

Your product is replaced by a refurbished or as new product, shipped to you on the same day that you report a fault. Advance RBEs carry a 6-month warranty.

Replace new

Your product is replaced by a new product, carrying a new factory warranty.

Please note:

The services offered on each product vary – please consult the detailed list that follows.

On Advance RBE, in order to get you a replacement product as soon as possible, it is necessary to charge a small additional premium on top of the price of the product to cover additional administration.

Available repair services for Specials are quoted per job.

All the following prices are for guidance only. When units are received with excessive wear and tear, or obsolete product is returned for repair, Renishaw reserves the right to quote a different service/replacement charge.

Advance replacements

Advance replacement is a Renishaw premium service aimed at minimizing your downtime. This service is only available on products where a Repair By Exchange (RBE) service is offered. Through this service we ship an RBE in advance of receipt of your inoperative product.

Please note:

- 1) A \$116 charge applies to each advance replacement.
- 2) Your inoperative product must be returned to Renishaw within 14 working days of receipt of the advance replacement.
- 3) Failure to do so will result in an issuance of a non-return invoice in the amount of the difference between the RBE price and the new list price.
- 4) Return of your inoperative product after the issuance of the non-return invoice will not result in a credit of the non-return invoice, and your inoperative product will be returned to you.
- 5) Advance replacements sent out under a warranty claim will not be credited if the returned product is damaged, or no fault is found with the returned product.
- 6) Returns of advance replacements will be accepted if:
 - a) they are returned unused, and in the original packaging, within ten working days of invoice date, and
 - b) the return has been pre-approved by Renishaw through the issuance of a Return Goods Authorization (RGA) number, and
 - c) the return passes Renishaw inspection, and
 - d) a re-stocking fee of \$116 or 20% is applied, whichever is the greater.

Coordinate Measuring Machine products

Manual probe heads

Description	Check and test	Repair	Repair by exchange	RBE part number
MH20	\$122	N/A	\$1,322	A-4043-0024-RBE
MH20i	\$122	N/A	\$1,684	A-4099-0022-RBE
MH8	\$122	N/A	\$917	A-1332-0002-RBE
MIH	\$272	N/A	\$2,384	A-1070-0003-RBE
PH1	\$122	N/A	\$664	A-1049-1795-RBE
PH5	\$122	N/A	N/A	Call for upgrade options
PH6	\$122	N/A	N/A	Replace at new list price

Motorized and servo positioning heads

Description	Check and test	Major repair	Repair by exchange	RBE part number
REVO®	N/A		Call for upgrade options	
REVO2	\$580	\$8,250	\$12,493	A-5759-0001-RBE
PH20	\$580		\$4,979	A-5669-0001-RBE
PH9/PH9A	Obsolete		Call for upgrade options to PH10 system	
PH10M	\$580	N/A	N/A	Call for upgrade to PH10 Plus
PH10MQ	\$580	N/A	N/A	Call for upgrade to PH10 Plus
PH10T	\$580	N/A	N/A	Call for upgrade to PH10 Plus
PH10M Plus	\$580	\$2,825	\$6,180	A-5863-1000-RBE
PH10T Plus	\$580	\$2,825	\$6,180	A-5863-2000-RBE
PH10MQ Plus	\$580	\$2,825	\$6,180	A-5863-3000-RBE
Description			Repair by exchange	RBE part number
PHS-2 RBE			\$15,224	A-5795-0001-RBE
PHS			Call for upgrade options to PHS-2	

Controllers

Description	Calibration	Repair	Repair by exchange	RBE part number
ACC2 (upgrade to ACC2-3)	N/A	N/A	\$1,340	A-6299-0100-RBE
ACC2-2 (upgrade to ACC2-3)	N/A	N/A	\$1,340	A-6299-0100-RBE
ACC2-3	N/A	M/A	\$1,340	A-6299-0100-RBE
PHC9/RS232	Obsolete		Call for upgrade options to PH10 system	
PHC9/IEEE	Obsolete		Call for upgrade options to PH10 system	
PHC10/RS232 (upgrade to PHC10-3 Plus)	N/A	N/A	\$1,340	A-5863-0100-RBE
PHC10-2/RS232 (upgrade to PHC10-3 Plus)	N/A	N/A	\$1,340	A-5863-0100-RBE
PHC10-3 Plus	N/A	N/A	\$1,340	A-5863-0100-RBE

Probes


Description	Price	Repair	Repair by exchange	RBE part number
Probe recertification (check and test)	\$122			
Description		Repair	Repair by exchange	RBE part number
SP25M probe body		N/A	\$2,105	A-2237-1000-RBE
SM25-1 module		N/A	\$1,503	A-2237-1111-RBE
SM25-2 module		N/A	\$1,503	A-2237-1112-RBE
SM252-U module		N/A	\$1,503	A-2237-1122-RBE
SM25-3 module		N/A	\$1,503	A-2237-1113-RBE
SM25-4 module		N/A	\$1,714	A-2237-1114-RBE
SM25-5 module		N/A	\$2,245	A-2237-1115-RBE
TM25-20 module		N/A	\$834	A-2237-1200-RBE
SP600M		N/A	\$4,973	A-2098-0104-RBE
TP1S		N/A	\$1,117	A-1041-7540-RBE
TP1SM		N/A	\$1,117	A-1041-7541-RBE

Probes continued

Description	Repair	Repair by exchange	RBE part number
TP2-5W	N/A	\$1,123	A-1042-1890-RBE
TP6	N/A	\$1,117	A-1039-0001-RBE
TP6A	N/A	\$1,117	A-1039-0028-RBE
TP7M	N/A	\$1,558	A-1073-0121-RBE
TPES	N/A	\$882	A-1311-0033-RBE
TP20 low force probe module only	N/A	\$1,087	A-1371-0392-RBE
TP20 standard force probe module only	N/A	\$1,087	A-1371-0270-RBE
TP20 medium force probe module only	N/A	\$1,087	A-1371-0271-RBE
TP20 extended force probe module only	N/A	\$1,087	A-1371-0272-RBE
TP20 6-way probe module only	N/A	\$1,207	A-1371-0419-RBE
EM1 TP20 extension module	N/A	\$1,207	A-1371-0430-RBE
EM2 TP20 extension module	N/A	\$1,207	A-1371-0431-RBE
TP20 body only	N/A	\$834	A-1371-0275-RBE
TP20 body (non-inhibit)	N/A	\$834	A-1371-0636-RBE



TP200 stylus module	N/A	N/A	Replace at new list price
TP200 probe sensor	N/A	\$1,328	A-1207-0020-RBE
TP200B probe sensor	N/A	\$1,328	A-1207-0046-RBE



Description	Check and test	Repair by exchange	RBE part number
SP80	\$175	\$6,107	A-2238-0101-RBE
SP80H	\$175	\$6,107	A-2238-0414-RBE

Interfaces

Description	Repair	Repair by exchange	RBE part number
PI7-3	N/A	N/A	Replace at new list price
PI200-3	N/A	N/A	Replace at new list price

Machine checking gage

Description	Calibration
Small checking gage set (includes arms, pivot and stylus; excludes needed replacement items)	\$530
Large checking gage set (includes arms, pivot and stylus; excludes needed replacement items)	\$554

(The machine checking gage is sent to the UK for calibration.)


Changing systems

Description	Calibration	Minor repair	Major repair	Repair by exchange	RBE part number
ACR1	\$541	\$1,099 (port replacement only)	N/A	\$6,096	A-1051-4000-RBE
ACR2	N/A	N/A	N/A	N/A	Replace at new list price
ACR3	N/A	\$489 (port replacement only)	N/A	\$3,530	A-5036-0005-RBE
FCR25	N/A	\$435 (port replacement only)	N/A	\$839	A-2237-1401-RBE
(for use with MRS)					
FCR25-L3	N/A	\$435 (port replacement only)	N/A	\$1,255	A-2237-1403-RBE
MCR20	N/A	\$532 (port replacement only)	N/A	\$1,322	A-1371-0163-RBE
SCR600	N/A	N/A	N/A	\$2,493	A-2098-0724-RBE
SCR200	N/A	\$1,401 (port replacement only)	N/A	\$2,493	A-1207-0031-RBE

Machine Tool products

Inspection probes for machining centers

Description	Price			
Recertification (check and test)	\$122			
Description	Repair	Repair by exchange	RBE part number	
CP1 probe	Obsolete	Call for upgrade options		
MP1/R probe	Obsolete	Call for upgrade options		
MP1/S probe	Obsolete	Call for upgrade options		
MP3 probe	N/A	\$947	A-2053-5358-RBE	
MP3 wide angle OMP short arm	Obsolete	Call for upgrade options		
MP3 wide angle OMP long arm	Obsolete	Call for upgrade options		
MP3 360° OMP	Obsolete	Call for upgrade options		
MP12 probe	Obsolete	Call for upgrade options		
MP16 (RMP2)	N/A	Call for upgrade options		
MP15	N/A	\$1,063	A-2116-0621-RBE	
MP15F	N/A	\$1,063	A-2116-0685-RBE	
MP700 probe module	Obsolete	Call for upgrade options		
MP700 OMP 35°	Obsolete	Call for upgrade options		
MP700 OMP 70°	Obsolete	Call for upgrade options		
MP7/8/9/10 optical systems	Obsolete	Call for upgrade options		
OMP40	N/A	\$1,461	Legacy: A-4071-0001-RBE Modulated: A-4071-2001-RBE	
OMP400	N/A	\$2,076	Legacy: A-5069-0001-RBE Modulated: A-5069-2001-RBE	
OMP60	N/A	\$1,461	Legacy: A-4038-0001-RBE Modulated: A-4038-2001-RBE	
OMP600	N/A	\$1,992	A-5180-2001-RBE	
RMP40	N/A	\$1,865	A-6588-0001-RBE	
RMP60	Obsolete	N/A	Replace with A-5742-0001-RBE	
RMP60Q	N/A	\$1,944	A-6587-0001-RBE	
RMP60MQ transmission module	N/A	\$1,165	A-6587-1001-RBE	
RMP600	N/A	\$2,330	A-6554-0001-RBE	
OMP60M/RMP60M probe module	N/A	\$1,099	A-4038-1002-RBE	
OMP60M transmission module	N/A	\$905	A-4038-1003-RBE	
RMP400	N/A	\$2,330	A-6586-0001-RBE	
Description	Check test	Repair by exchange	RBE part number	
MSP80 rear exit	\$520	\$15,088	A-2238-1255-RBE	
MSP80 side exit	\$520	\$15,088	A-2238-1270-RBE	



Tool setting probes for machining centers

Description	Repair	Upgrade	Upgrade part number
MP4 side exit (obsolete, upgrade to TS34 side exit)	N/A	\$2,765	RI-2197-3000
MP4 rear exit (obsolete, upgrade to TS34 rear exit)	N/A	\$2,765	RI-2197-2100
MP6 base only	N/A	N/A	Replace at new list price

Description	Rewire	Repair by exchange	RBE part number
TS20	N/A	N/A	Replace at new list price
TS27R	\$255	\$1,075	A-2008-0368-RBE
TS34 rear exit	N/A	\$1,225	A-2197-2100-RBE
TS34 side exit	N/A	\$1,225	A-2197-3000-RBE

Description	Repair	Repair by exchange	RBE part number
All NC4 fixed compact and modular variants	N/A	N/A	Call for replacement options
All NC4+ fixed compact variants	N/A	N/A	Call for replacement options
All NC4 fixed IAB Red LED with connector variants	N/A	N/A	Call for replacement options
All NC4+ fixed IAB Red LED with connector variants	N/A	N/A	Call for replacement options
NC4 generic TX (separate – no access panel)	N/A	\$1,274	A-4114-5200-RBE
NC4 generic RX (separate – no access panel)	N/A	\$1,274	A-4114-5300-RBE
NC4 TX (separate with connector – no access panel)	N/A	\$1,274	A-4114-2345-RBE
NC4 RX (separate with connector – no access panel)	N/A	\$1,274	A-4114-2346-RBE
NC4+ F115 IAB H31 Red LED with integral cable	N/A	\$2,655	A-6270-2000-RBE
NC4+ F145 IAB H31 Red LED with integral cable	N/A	\$2,655	A-6270-2200-RBE
NC4 F230 IAB H31 Red LED with integral cable	N/A	\$2,655	A-6270-2400-RBE
NC4 F300 IAB H31 Red LED with integral cable	N/A	\$2,655	A-6270-2600-RBE
NC4 F300 IAB H50 Red LED with integral cable	N/A	\$2,655	A-6270-2700-RBE
NC4+ F115 IAB H31 Blue LED with connector	N/A	\$3,031	A-6435-2010-RBE
NC4+ F115 IAB H31 Blue LED with integral cable	N/A	\$3,031	A-6435-2020-RBE
NC4+ F145 IAB H31 Blue LED with integral cable	N/A	\$3,031	A-6435-2200-RBE
NC4+ F145 IAB H31 Blue LED with connector	N/A	\$3,031	A-6435-2210-RBE
NC4+ F230 IAB H31 Blue LED with integral cable	N/A	\$3,031	A-6435-2400-RBE
NC4+ F230 IAB H50 Blue LED with connector	N/A	\$3,031	A-6435-2510-RBE
NC4+ F300 IAB H50 Blue LED with connector	N/A	\$3,031	A-6435-2710-RBE
NCPCB	N/A	N/A	Replace at new list price
OTS	N/A	\$1,207	A-5401-2001-RBE
OTS (AA)	N/A	\$1,304	A-5514-2001-RBE
TRS2	N/A	\$815	A-5450-0400-RBE
RTS-QE	N/A	\$1,979	A-5646-0001-RBE

Inspection probes for turning centers

Description	Repair	Repair by exchange	RBE part number
LP2 probe	N/A	\$960	A-2063-6098-RBE
LP2DD probe	N/A	\$960	A-2063-8020-RBE
LP2H probe	N/A	\$960	A-2064-0002-RBE
LTO2	Obsolete	Call for upgrade options	
LTO2S	Obsolete	Call for upgrade options	
LTO2T (25 mm shank)	Obsolete	Call for upgrade options	
LTO2T (1 in shank)	Obsolete	Call for upgrade options	
LTO3T (25 mm shank)	Obsolete	Call for upgrade options	
LTO3T (1 in shank)	Obsolete	Call for upgrade options	
MP250	N/A	\$1,304	A-5500-1600-RBE
OLP40	N/A	\$1,454	A-5625-2001-RBE
OMP40M	N/A	\$930	A-5626-2001-RBE
RLP40	N/A	\$1,992	A-6717-0001-RBE
RMP40M	N/A	\$1,165	A-6716-0001-RBE

Tool setting arms

Description	Repair	Repair by exchange	RBE part number
HPRA 6 in with RP3	N/A	\$1,859	A-2176-0691-RBE
HPRA 8 in with RP3	N/A	\$1,859	A-2176-0692-RBE
HPRA 10 in with RP3	N/A	\$1,859	A-2176-0693-RBE
HPRA 12 in with RP3	N/A	\$1,859	A-2176-0694-RBE
HPRA 15 in with RP3	N/A	\$1,859	A-2176-0695-RBE
HPRA 18 in with RP3	N/A	\$1,859	A-2176-0697-RBE
HPRA 24 in with RP3	N/A	\$1,859	A-2176-0698-RBE
HPPA 6 in rear exit with RP3	N/A	\$2,197	A-2275-0230-RBE
HPPA 8 in rear exit with RP3	N/A	\$2,197	A-2275-0231-RBE
HPPA 10 in rear exit with RP3	N/A	\$2,197	A-2275-0232-RBE
HPPA 12 in rear exit with RP3	N/A	\$2,197	A-2275-0233-RBE
HPPA 15 in rear exit with RP3	N/A	\$2,197	A-2275-0234-RBE
HPPA 18 in rear exit with RP3	N/A	\$2,197	A-2275-0235-RBE
HPMA 6 in rear exit with RP3	N/A	\$2,475	A-2181-0645-RBE
HPMA 8 in rear exit with RP3	N/A	\$2,475	A-2181-0646-RBE
HPMA 10 in rear exit with RP3	N/A	\$2,475	A-2181-0647-RBE
HPMA 12 in rear exit with RP3	N/A	\$2,475	A-2181-0648-RBE
HPMA 15 in rear exit with RP3	N/A	\$2,475	A-2181-0649-RBE
HPMA 18 in rear exit with RP3	N/A	\$2,475	A-2181-0650-RBE
HPMA 24 in rear exit with RP3	N/A	\$2,475	A-2181-0651-RBE
HPGA (side exit 90° connector)	N/A	\$2,396	A-5616-0352-RBE
HPGA (side exit straight connector)	N/A	\$2,396	A-5616-0101-RBE

Tool setting probes for turning centers

Description	Repair	Repair by exchange	RBE part number
RP1 probe	N/A	\$923	A-2154-0007-RBE
RP2 probe	N/A	\$923	A-2116-0149-RBE
RP3 probe	N/A	\$923	A-2197-0049-RBE
TS20 probe	N/A	N/A	Replace at new list price

Interfaces, receivers and inductive systems

Description	Repair	Repair by exchange	RBE part number
HSI	N/A	N/A	Replace at new list price
IMM (inductive module machine)	N/A	N/A	Obsolete – call for upgrade options
IMP (inductive module probe) assembly	N/A	N/A	Obsolete – call for upgrade options
MI5	N/A	N/A	Obsolete – call for upgrade options
MI8	N/A	N/A	Obsolete – replace with HSI interface at list price
MI8-4	N/A	N/A	Replace at new list price
MI12	N/A	N/A	Obsolete – call for upgrade options
NCi interface	N/A	N/A	Replace at new list price
OMI	N/A		Obsolete – call for upgrade options
OMI-2	N/A	\$1,020	A-5191-0050-RBE
OMI-2T	N/A	\$1,020	A-5439-0050-RBE
OMM	N/A		Obsolete – call for upgrade options
OMM-2	N/A	\$815	A-5492-0051-RBE
RMI	N/A	\$1,155	Replace with A-5687-0050-RBE
RMI-Q	N/A	\$1,207	A-5687-0050-RBE
RMI-QE	N/A	\$1,207	A-6551-0049-RBE
SSR converter board	N/A	N/A	Obsolete – replace with HSI interface at list price
TSi interface	N/A	N/A	Replace at new list price
OSI interface	N/A	N/A	Replace at list price

Gauging systems

Description	Repair	Repair by exchange	RBE part number
Equator™ 300 machine	\$9,686	\$12,614	A-5504-0040-RBE
Equator™ 300 extended height machine	\$9,686	\$13,277	A-5504-0050-RBE
Equator™ controller	N/A	\$3,794	A-5696-0101-RBE
SP25M body	N/A	\$2,105	A-2237-1000-RBE
SM25-2 module	N/A	\$1,503	A-2237-1112-RBE
Equator™ 500 machine	Call for repair options and pricing		

Calibration systems

Renishaw recommends the following calibration frequencies:	XM-60	Every 1-2 years
	ML10/ML10X/XL-80	Every 2-3 years
	EC10/XC-80	Every 12 months
	Ballbar	Every 12 months
	RX10	Every 2-3 years
	XR20	Every 1-3 years
	XK10	Every 2 years

Check and test \$382

Repair prices

Description	Repair	Repair by exchange
XC-80	\$2,615	N/A
XL-80	\$2,615	N/A
XL-80 tripod	\$455	N/A
XR20**	N/A	\$7,874
RX10	Call for upgrade options	N/A
QC10 ballbar (mechanical assembly only)	Call for upgrade options	N/A
QC20 (mechanical assembly only)	N/A	\$3,880
XK10	Call for pricing	Call for pricing
XM-60	Call for pricing	N/A

Calibration prices

	Standard calibration	Express calibration
QC20 (includes calibrator)	\$989	\$1,121
QC10 (includes calibrator)	\$989	\$1,121
50 m calibrator (glass only)	\$339	\$471
50 mm calibrator kit for QC20	\$489	\$621
50 mm calibrator kit for QC10	\$794	\$926
300 mm calibrator (glass only)	\$380	\$512
XC-80 *	\$1,253	\$1,421
XL-80	\$1,253	\$1,421
ML10/ML10X	\$1,253	\$1,421
EC10 *	\$1,253	\$1,421
XM-60/XM-600	\$4,989	N/A
XK10	\$3,616	N/A
RX10	Call for upgrade options	N/A
XR20**	\$1,736	N/A
Copy of calibration certificate	\$168	

* Price includes one air sensor and up to three material sensors. Each additional sensor \$334. Please send in your sensors with your EC10 and XC-80.

** XR20 must be shipped in proper packaging. Failure to do so could damage unit and delay return after service. Alternative packaging solutions other than the XR20 case are available for purchase which provide protection for your unit and save transport costs. XR20W-CAL-BOX is an economic and safe alternative to shipping XR20 in its case. The packaging is reusable and can be purchased for \$83.

A “standard” calibration will take a maximum of five working days and an “express” calibration will take a maximum of two working days. Express calibrations must be scheduled by calling the Renishaw Service Center at: 847/286-9953 extension 62123.

Ballbar calibration includes ballbar and calibrator calibration, and replacement of ball and mount assembly, center cup assembly, center ball assembly, and tool cup assembly. A new cleaning kit will also be supplied.

Traceable calibration certificates will be issued at the time of calibration and enclosed with the returned units.

Industrial automation products

Renishaw recommends the following calibration frequency:

RCS Calibrator	Every 12 months
RCS L-90	Every 12 months
Check and test	\$400
Calibration certificate reprint	\$116

Repair prices

Description	Repair	Repair by exchange
RCS L-90	N/A	\$5,392
RCS T-90 frame balls	N/A	\$726

Calibration prices

RCS L-90	\$1,584
RCS Calibrator	\$1,132
RCS L-90 full kit calibration*	\$2,716
RCS T-90 full calibration**	\$4,980

* Price includes calibration for one RCS calibrator and one RCS L-90 strut.

** Price includes calibration for one RCS calibrator and three RCS L-90 struts.

RCS L-90 calibration includes complete cleaning, replacement of strut joints and seals, full unit function check and calibration.

Traceable calibration certificates will be issued at the time of calibration and enclosed with the returned units.

Shipping with original Renishaw kit packaging is recommended. Any damaged caused by inappropriate packing could delay the return service.

Replacement parts

Description	Part number	Price
ACR1/ACR3 short port replacement kit	A-5036-0049	\$343
ACR1 long port replacement kit	A-1051-7077	\$332
ACR1 mixed port replacement kit	A-1051-7076	\$332
MP3/MP6 probe outer diaphragm kit	A-2053-8156	\$121
LP2 service kit	A-2063-7542	\$97
Ballbar center cup assembly	A-8014-0522	\$215
Ballbar center ball assembly	A-8014-0141	\$190
Ballbar magnetic tool cup	A-8014-0521	\$171
Transducer ball	A-8014-0182	\$190
Ballbar cleaning kit	A-8014-0423	\$26
Ballbar service kit	A-8014-0786	\$582
OMP40 pull-up cone assembly	A-4071-0094	\$52
OMP40 round battery cap with seal	A-4071-0096	\$121
OMP40 rectangular battery cassette	A-4071-1166	\$163
OMP40/OMP60/RMP60 battery cassette seal	A-4038-0301	\$36
OMP60/RMP60 battery cassette	A-4038-0300	\$246
OMP60/RMP60 outer diaphragm kit	A-4038-0302	\$96
OMP60/RMP60 shank switch bobbin	A-4038-0303	\$223
OMP60/RMP60 new type shank switch	A-4038-0177	\$219
OMP60/RMP60 cone puller kit	A-4038-CONE-KIT	\$44
OLP40/RLP40 eyelid service kit	A-5625-0005	\$34
OLP40/RLP40 metal battery cassette	A-5625-1166	\$184
OLP40/RLP40 front cover	M-5625-0113	\$36
OTS/RTS battery cap	A-5401-0301	\$207
OTS/RTS base assembly	A-5401-0350	\$140
TS27R front cover	A-2008-1015	\$109
TS27R base and plinth kit	A-2008-1018	\$140
OTS/RTS front cover kit	A-5401-8512	\$155
TS34 chip shield	A-2008-6007	\$155
OMI-2/OMM-2 window kit	A-5191-0019	\$154
1/4 in conduit, 1 meter unit	P-CF01-0001	\$29 per meter
1/4 in conduit gland/fitting	M-2028-7456	\$15
Locknut for 1/4 in conduit gland/fitting	M-2028-7459	FOC
5/16 in conduit, 1 meter unit, modulated optical/radio receivers	P-CF01-0004	\$29 per meter
5/16 in conduit gland with locknut	A-4113-0307	\$15
GP9 conduit, 1 meter unit, NC4 IAB/Blue with cable connector	P-HO01-0010	\$29 per meter
GP9 conduit gland/fitting	A-6270-0383	\$31
GP11 conduit, 1 meter unit, NC4 separate	P-HO01-0008	\$29 per meter
GP11 conduit gland/fitting	P-CA61-0063	\$42
GP16 conduit, 1 meter unit, NC4F legacy, hard-wired	P-HO01-0011	\$29 per meter
GP16 conduit gland/fitting	P-CA61-0065	\$108
GP18 conduit, 1 meter unit, NC4 IAB hard-wired	M-6270-0278	\$29 per meter
GP18 conduit gland/fitting	M-6270-0277	\$145
Locknut for GP9/11/16/18 conduit gland/fitting	P-NU03-0200	\$2
TP200 cleaning kit	A-1085-0016	\$23

