

**LLANTWIT FARDRE COMMUNITY COUNCIL  
CYNGOR CYMUNED LLANILLTUD FAERDREF**



**COUNCIL MEETING**

**30<sup>th</sup> June 2025**

**REPORT OF CLERK**

**1. PATHWAY TO YSGOL TY COCH PLAY AREA**

- 1.1 Members will recall at the previous meetings of the Leisure and Amenities Committee the Clerk presented a report in relation to laying a new outer path to the play area.
- 1.2 At the meeting of Leisure and Amenities held on the 10<sup>th</sup> March 2025 Members resolved that Officers obtain further information as to where the overlay of the pathway would be sufficient or a complete removal and lay new path. As seen in the Table below.

| Company   | Cost        | Explanation provided form suppliers  |
|-----------|-------------|--|
| Company A | £4,639 +VAT | Breakdown and remove old tarmac and install flexi path                     |
| Company B | £2860+VAT   | Cut back and clean existing pathway and overlay with 30mm conipave         |
| Company C | £2020+ VAT  | Repair works, overlay with rubberstone high tensile @35mm and safety fence |

- 1.3 Officers have been in communication with the pathway installation teams and they have confirmed that by overlaying a damaged pathway with rubberstone high tensile surface which is technically designed for. The pathway will be cleaned, any loose stone areas removed or repaired. Any areas that need repairing will be worked on. The area is then fully primed which allows the surface to fill any small gaps and stick to the base, the surface is then laid which results in a pathway which is more flexible, robust, non-slip surface that does not break or crack.
- 1.4 As Members can see from the information in 1.3 of the report that proceeding with repair work is a safe option

## **2. RECOMMENDATIONS**

- 2.1 Members are requested consider the report.
- 2.2 If Members agree to proceed with the works, Members will need to agree the cost and Company they wish to use