2025 Solar Hills Ranch Irrigation System Reserve Study Update (September, 2025)
On 9/14/2025 the \$100 Special Assessment was renewed for 2026. A quorum of 25 lots (60%) was required; quorum was met. The tally was 27 yes, one no. The board also approved to increase funding from \$36,000 to \$100,000. NOTE: Some asset numbers/values have changed due to verification and repairs and will not match those from the 2019 study.

Asset Replacement Values 2025

Descriptions	Linear Feet	Unit Price	Total Value
2 inch Schedule 40 PVC	80	\$1.88	\$150.40
4 inch Schedule 40 PVC	1,568	\$4.86	\$7,620.48
6 inch Schedule 40 PVC	1,640	\$9.73	\$15,957.20
8 inch Schedule 40 PVC	5,172	\$15.14	\$78,304.08
10 inch Schedule 40 PVC	156	\$26.15	\$4,079.40
12 inch Schedule 40 PVC	96	\$32.14	\$3,085.00
(no labor included) Subtotal	8,712		\$109,196.56

Drain pipes

2 inch PVC Schedule 40 PVC	206	\$1.88	\$387.28
4 inch PVC Schedule 40 PVC	335	\$4.86	\$1,628.10
8 inch PVC Schedule 40 PVC	471	\$15.14	\$7,130.94
(no labor included) Subtotal	1,012		\$9,146.32

	Quantity	Unit Price	Total Value
Air Vac	18	\$80.00	\$1,440.00
10 inch Tee	1	\$600.00	\$600.00
8 inch Tee	9	\$200.00	\$1,800.00
6 inch Tee	5	\$50.00	\$250.00
2 inch reducer Tee's (approx.)	60	\$50.00	\$3,000.00
(no labor included) Subtotal			\$7,090.00

NOTE: Does not include reducers

12 inch Waterman Valve	1	\$4,173.00	\$4,173.00
10 inch Gate Valve	1	\$2,300.00	\$2,300.00
8 inch Gate Valve	5	\$1,673.00	\$8,365.00
6 inch Gate Valve	2	\$1,106.00	\$2,212.00
4 inch Gate Valve	4	\$400.00	\$1,600.00
2 inch Ball Valve	3	\$40.00	\$120.00
(no labor included) Subtotal			\$18,770.00

Drain Box	1	unknown	
Dock Replacement		unknown	
Subtotal			

Estimated Total Value of Assets		\$144,202.00
---------------------------------	--	--------------

Estimated Labor Costs for Pipe Replacement Only

Trenching Labor - \$12/running ft		\$116,664.00
-----------------------------------	--	--------------

Solar Hills Ranch Irrigation Reserve Study Update - September, 2025

Page 2

Physical Assets 2025

Irrigation System Assets	Units	Condition	Comments
Isolation Water Valves			
12 inch Waterman valve	1		
10 inch	1		replaced 2025
8 inch	6	33 years old 1/2 life expectancy	
6 inch	2	33 years old 1/2 life expectancy	
4 inch	2	33 years old 1/2 life expectancy	new valve installed 1995

12

Drain Valves			
8 inch	2	Fair PVC sewer pipe	Installed 2001
6 inch	1	Fair PVC sewer pipe	Installed 2001
4 inch	4	Fair PVC conduit	replaced 2022
2 inch	1	Fair PVC sewer pipe	Abandoned
Drain box for East Ditch 18"			Installed 2011

5

Air Vacs	18	Good condition, most of them have been repaired	
All vacs	10	Good Condition, most of them have been repaired	i

Pipelines (irrigation and drain			
lines)	Linear Feet		
12 inch Schedule 40 PVC	96		
10 inch Schedule 40 PVC	156		
8 inch Schedule 40 PVC	5643	includes drain lines	
6 inch Schedule 40 PVC	1640		
4 inch Schedule 40 PVC	1903	includes drain lines	
2 inch Schedule 40 PVC	206		
NOTE: Total lengths is approximate	9644		

Pond weir (head gate)		UVWUA responsible
Pond ditch exit gates		
Dock - currently 490 sq feet		

	Number of		
Additional Pipe Assets	items	Comments	Lot
		each lot has a single 2inch tee that connects to	
2 inch Tee	41	main	all lots
10" - 12" elbow (90)	1		Lot 18
		One is for main line (lot 21) and other is a drain (lot	
4" elbow (90)	2	4)	Lots 2 - 21
10 x 10 x 10 Tee	1	main line delivery	Lot 21
8 x 8 x 8 Tee	3	One is for main and Lots 6/7 and 42 are drains	Lots 6/7 - 37 - 42
8 x 6 x 8 Tee	2	Inner loop tees	Lots 23 - 42
8 x 8 x 4 Tee	2	main line	Lots 3 - 15
8 x 4 x 8 Tee	1	main line	Lot 37
6 x 4 x 6 Tee	1	for 4" drain	Lot 27