

Electromagnetic Clutches & Brakes





Typical Applications
Why They Work So We
Mobile Clutches
 Mobile Products
• Industrial Products
PRODUCTS MENU

Installation Procedures Troubleshooting Clutch Will Not Disengage

Clutch Will Not Engage Clutch Slips

Noisy Clutch **Mobile Models/Dimensions**

General Purpose PTO Clutch/Brake

Air Blower Products

Home About What's New Technical Contact Us Links Search Home » Mobile Products » Troubleshooting » Clutch Will Not Disengage

Potential Problem Voltage not releasing.

Rotor and armature locked together.

Pulley bearing locked.

clutch will still not engage.

Voltage is going to the clutch but the

Possible Reason

Faulty switch.

The clutch has been severely galled and has locked up. (Galling is the condition whereby a piece of metal is trapped between the armature and the rotor and melts due to high pressure and heat, spot welding the surfaces together.)

Bearing lost grease due to seal problem, temperature or water contamination. (Example)

The air gap is too large. (Example)

Solution

Replace switch.

If rotor and armature connot be separated, replace the clutch. If they do $% \left(1\right) =\left(1\right) \left(1$ separate, follow burnishing procedure.

Replace clutch.

If straight bore the air gap can be readjusted. If unit has set screw, bottom out armature hub against field then back off to 0.1 inches and retighten set screw. If spacers are used on straight bore reduce the width of the spacer. If it's a taper bore clutch tap on the armature cover plate to close air gap.



About Us

- Profile
- Video Segments
- Other Ogura Companies

What's New

- Latest News
- Magazine Editorials
 Recent Press Releases
- Ogura Quarterly
- Newsletter
- Trade Magazine Ads

Technical

- Formula Worksheet (PDF)
- Conversion Calculators

Contact Us

- Sales Representatives
- General Inquiry Form
- Application Form Information

Links

- Industry and Reference
- Company Associations

© 2013 Ogura Industrial Corp. All rights reserved.

Ogura Industrial Corp • 100 Randolph Road • Somerset, New Jersey 08873 Phone: 732-271-7361 • Fax: 732-271-7580 • info@ogura-clutch.com

The contents of this website are protected under US copyright laws. This site has been issued a certificate of registration by the United States copyright office, registration #TX 6-426-894