



ATTACH HF12-23 AUGER SHIELD TO MOTOR END OF FEEDER. THIS WILL LEAVE THE DISCHARGE END OF THE AUGER OPEN.

ATTACH HF12-23 AUGER SHIELD AND TRANSFER LEFT END HOLES. DRILL USING  $\varnothing 9/32$  BIT.

ATTACH SHIELD USING  $1/4-20 \times 1$  BOLTS, FLAT WASHERS AND LOCK WASHERS.

## TRIPLE C, INC.

P.O. BOX 248, SABETHA, KS 66534  
(785) 284-3674 FAX (785) 284-3931

MATERIAL:

X

DWG PATH: \DWG\HF12

DO NOT SCALE  
DRAWING

SHEET  
\_\_ OF \_\_

SCALE:  
1/8

DRAWN BY:  
CEDRIC HEINIGER  
04/18/97

TOLERANCES  
Unless otherwise specified

XX .010  
XXX .005  
XXXX .0005  
X/X 1/32  
ANGLE 0°30'

TITLE:

AUGER SHIELD  
INSTALLATION

DRAWING NUMBER:  
HF12-24

REV  
B