

<b><u>Kubota Tractor Models</u></b>	<b>No. Of Filters</b>	<b>OEM Part Numbers</b>	<b>FlowClean Filter Number</b>	<b>New RRP \$ + GST</b>	<b>Recharge RRP \$ + GST</b>
59/50 Original Cab 5970	1	336919/50310	<b>T441/T645</b>	<b>\$291.50</b>	<b>\$204.05</b>
59/50 Gason Cab	1		<b>T491</b>	<b>\$462.00</b>	<b>\$323.40</b>
L4850 M5970 Air Freeze Cab	1	804121	<b>T450</b>	<b>\$308.00</b>	<b>\$215.60</b>
6020 M6950 M6970 M90 M110 M120 M7580 M7970 M8580 M8970 M9580	2	36919/50310	<b>T441/T645</b>	<b>\$291.50</b>	<b>\$204.05</b>
6030 M4050 M4030	1		<b>T496</b>	<b>\$442.20</b>	<b>\$309.54</b>
6030DT M7030 Air Freeze Cab	2	804121	<b>T450</b>	<b>\$308.00</b>	<b>\$215.60</b>
M6950DT M8950DT	1		<b>T546</b>	<b>\$418.00</b>	<b>\$292.60</b>
6970DT M8950	2		<b>T495/T645</b>	<b>\$291.50</b>	<b>\$204.05</b>
M90 DTC	2	52241/21650	<b>T645</b>	<b>\$291.50</b>	<b>\$204.05</b>
Silvan Sprayers - Kasco Brand	1		<b>T533</b>	<b>\$462.00</b>	<b>\$323.40</b>
L4200 Cab/some are not	1		<b>T562</b>	<b>\$349.65</b>	<b>\$244.76</b>
M4900 M5700 M6800 M8200 ME8200 ME9000 M7132 M8540 M9540 L4310 L5030 M95S M105S B3030 L5740 M135GX	1	T1855-71600, TA043-71600, TA055-71600, 3B794-71603, T185571600, TA04371600, TA05571600, 3B79471603, T1855-71600, TA043-71600, TA055-71600, T185571600, TA04371600, TA05571600, T1855-71600, TA043-71600, TA055-71600, 3B794-71602, 3B794-71603, T185571600, TA04371600, TA055716003, B79471602, 3B79471603, 1A703087990	<b>T571</b>	<b>\$304.50</b>	<b>\$213.15</b>
M8200 Narrow	1		<b>T503</b>	<b>\$351.75</b>	<b>\$246.23</b>
M95X M105X M126X M125X	2	52241/21650	<b>T645</b>	<b>\$291.50</b>	<b>\$204.05</b>
M8540 Narrow (with seal)	1	W2336-71600	<b>T655</b>	<b>\$351.75</b>	<b>\$246.23</b>
9540 Recirc; KX040-4 (excavator)	1	6A6715090	<b>T746</b>	<b>\$117.60</b>	<b>\$82.32</b>

<i>Kubota Tractor Models</i>	<i>No. Of Filters</i>	<i>OEM Part Numbers</i>	<i>FlowClean Filter Number</i>	<i>New RRP \$ + GST</i>	<i>Recharge RRP \$ + GST</i>
RTVX1100C	1		<b>T753</b>	<b>\$189.00</b>	<b>\$132.30</b>
KX 080-3, KX 080-3 ALPHA, KX 080-4, KX 080-4 ALPHA, KX 080-4 ALPHA 2, R 065, R 082, R 085, KX175-5, KX183, KX185	1	CB-4002, KF60D001A, B222100000660K, T0270-67060, 60250669, 014300-3970, T0270-37061,	<b>T793</b>	<b>\$323.40</b>	<b>\$226.38</b>

**LANDINI/MASSEY FERGUSON**

<u><i>Landini/Massey Ferguson Tractor Models</i></u>	<i>No. Of Filters</i>	<i>OEM Part Numbers</i>	<i>FlowClean Filter Number</i>	<i>New RRP \$ + GST</i>	<i>Recharge RRP \$ + GST</i>
75F 85F Landini	1		<b>T506</b>	<b>\$434.70</b>	<b>\$304.29</b>
265 Gason Cab	1		<b>T515</b>	<b>\$379.50</b>	<b>\$265.65</b>
Massey	Round	V220pb2558212	<b>T776</b>	<b>\$539.00</b>	<b>\$377.30</b>
MF355 MF365	1		<b>T462</b>	<b>\$409.50</b>	<b>\$286.65</b>
MF355 Marlandair	1		<b>T483</b>	<b>\$330.75</b>	<b>\$231.53</b>
362,390,398,399	1	3478477M91	<b>T647</b>	<b>\$321.30</b>	<b>\$224.91</b>
<b>Filter Infront of Windscreen</b>					
362 390 398 399 Filter inside Cab	1	3478327M1	<b>T646</b>	<b>\$320.25</b>	<b>\$224.18</b>
375 390 398 399 Hi Line Cab	1	Has Lugs	<b>T516</b>	<b>\$341.00</b>	<b>\$238.70</b>
374S 394S 374 394F 3245 All Q Cabs	1	3311741M91	<b>T488</b>	<b>\$410.55</b>	<b>\$287.39</b>
542 SP Auto Header	1		<b>T530</b>	<b>\$341.25</b>	<b>\$238.88</b>
550 575 590 Gason Cab	1		<b>T436</b>	<b>\$424.60</b>	<b>\$297.22</b>
8650, 8670, 8680, 8690, 8730S	2	4284929M2, 4384415M2	<b>T706</b>	<b>\$355.95</b>	<b>\$249.17</b>
6,753,095	1	3405118M1	<b>T432</b>	<b>\$438.75</b>	<b>\$307.13</b>
690 698 699 6880 8880 Landini Cab	1	3302666M92	<b>T488</b>	<b>\$410.55</b>	<b>\$287.39</b>
698 699 Gason Cab	Round		<b>T491</b>	<b>\$462.00</b>	<b>\$323.40</b>