



## Turn Every Conveyor Sale Into Additional Revenue

**Custom catch cloths that fit any conveyor—and add value to every quote.**

Siftex Catch Cloths give conveyor resellers a simple, high-margin add-on that enhances system performance while increasing total sale value. Designed for bakery and food production environments, our catch cloths are fully custom-built to match each conveyor layout—no matter how complex.

You don't need to fabricate, stock, or engineer anything.

Provide the basics, and we'll design and manufacture the solution.

## Why Resellers Partner with Siftex

- **Consultative Engineering Support & Site Visits**

We collaborate with your engineering team—and your end users—to ensure proper fit, function, and repeatability

- **Unlimited Customization**

Straight runs, turns, funnels, boxes—or completely custom shapes. If it's not shown, we can still build it.

- **No Fabrication or Inventory Required**

We custom-build to order—you carry no stock and no production risk.

- **Fast Lead Times**

Custom solutions produced quickly to keep projects moving.

- **Drop Ship or Blind Ship Available**

We ship directly to your customer—on your terms.


- **One Trusted Supplier**

Reliable quality backed by decades of textile manufacturing experience.

**More flexibility. More margin. Zero hassle.**

Add custom catch cloths to your quote without slowing down the sale.


The examples shown represent common applications. Siftex specializes in custom designs and can build catch cloths for virtually any conveyor configuration. Provide basic measurements—we'll handle the rest.



## 45 Degree Turn

### Measurements Required (inches/mm):


- Width\*
- Inside Circumference or Outside Circumference
- Grommet Spacing



## 90 Degree Turn

### Measurements Required (inches/mm):


- Width\*
- Inside Circumference or Outside Circumference
- Grommet Spacing



## 180 Degree Turn

### Measurements Required (inches/mm):


- Width\*
- Inside Circumference or Outside Circumference
- Grommet Spacing



## Straight

### Measurements Required (inches/mm):


- Width\*
- Length
- Grommet Spacing



## Box

### Measurements Required (inches/mm):

- Width\*
- Depth
- Length
- Grommet Spacing



## Funnel

### Measurements Required (inches/mm):

- Width\*
- Depth
- Length
- Grommet Spacing

\*When providing catch cloth width, measure the outside of the conveyor frame width. We recommend a 2" sag, please make sure to add your desired sag to the frame width.

## Start Adding Catch Cloths to **Your Quotes**

- Get reseller pricing
- Add catch cloths to your next conveyor sale
- Ask about drop shipping options

### Customer Service


Phone: (800) 274-3839

Email: [customerservice@siftex.com](mailto:customerservice@siftex.com)

### Carleen Cunningham

Phone: (860) 999-9516

Email: [carleen@siftex.com](mailto:carleen@siftex.com)



**Learn More**