Rainier Fiber Premium Wood Fiber Mulch	Rainier Fiber Plus Tackifier	Rainier Fiber Bonded Fiber Matrix (BFM)	Rainier Supreme
4.0H:1.0V	3.0H:1.0V	≤ 1.0H:1.0V	≤ 0.25H: 1.0V
1,800 lbs/ac	2,500 lbs/ac	4,000 lbs/ac	4,500 lbs/ac
Not Tested	Not Tested	<.01	<.01
Not Tested	Not Tested	> 99.7%	> 99.9%
Not Tested	Not Tested	> 599%	>635%
1300%	1350%	1300%	>1600%
<3 months	3 - 5 months	> 12 months	> 18 months
1,800 lbs/ac from flat to 4.0H: 1.0V slope	2,000 lbs/ac from flat to 4.0H: 1.0V slope	Ranges from 2,500 lbs/ac at 3.0H: 1.0V to 4,000 lbs/ac at ≤ 1.0H: 1.0V	Ranges from 2,500 lbs/ac at 3.0H : 1.0V to 4,500 lbs/ac at ≤ 0.25H : 1.0V
	Fiber Mulch 4.0H: 1.0V  1,800 lbs/ac  Not Tested  Not Tested  Not Tested  1300%  < 3 months  1,800 lbs/ac from flat to 4.0H: 1.0V	Fiber Mulch         Rainier Fiber Plus Tackifier           4.0H: 1.0V         3.0H: 1.0V           1,800 lbs/ac         2,500 lbs/ac           Not Tested         Not Tested           Not Tested         Not Tested           Not Tested         Not Tested           1300%         1350%           < 3 months	Fiber Mulch         Rainier Fiber Plus Tackifier         Matrix (BFM)           4.0H: 1.0V         3.0H: 1.0V         ≤ 1.0H: 1.0V           1,800 lbs/ac         2,500 lbs/ac         4,000 lbs/ac           Not Tested         Not Tested         < .01

Pinnacle Erosion Control Supply ~ (509) 368-0700 ~ tkopp@PNWpinnaclesupply.com