

The header image features a dark, textured background on the left with the word 'THEOREM' in white. On the right, a woman is shown relaxing in a green recliner chair in a modern living room setting. The text 'FABRIC CARE GUIDE' is overlaid in large white letters across the middle of the image.

THEOREM

FABRIC CARE GUIDE

Theorem Power Lift Recliners has **three** upholstery groups in the range.

- Bonded PU: Winslow, Mercer, Seagrove, Sheffield, Cheshire
- Leather match: Abingdon, Ealing (100% leather on all touch-points — seat, back, arms, legrest — with matching PU elsewhere)
- Fabric (100% Polyester): Alperton, Ludlow, Marcos, Pembroke, Studio, Pinnacle (Sitting Pretty), Summit (Sitting Pretty)

All **fabric-upholstered** Theorem (including **Pinnacle** and **Summit**) chairs use **100% polyester yarn**. Theorem uses several different weaves and surface finishes to create diversity in the range, but the yarn used is always the same. The polyester fabric has an inherent stain-resistant quality — most marks can be removed with a clean damp cloth. A fabric protector may be used; test first on a hidden area.

The **leather match** chairs should be treated/cleaned as any leather chair, with a specific leather cleaner.

TWO-YEAR FABRIC WARRANTY

Theorem Power Lift Recliners guarantees to replace any fabric found to be faulty as a result of manufacturing defect and used in accordance with our performance ratings and care instructions. An evaluation of fabric-related issues must be conducted before confirmation of warranty coverage can be verified. Theorem recommends stain-resistant treatment before use.

CONSUMER WARRANTY AGAINST DEFECTS

Theorem does not warrant against excessive or incorrect use, modification or any situation that could not be deemed fair wear and tear. This is a back-to-base warranty and does not cover freight costs pertaining to the return of any items under warranty. Theorem acknowledges and conforms to all ACCC guidelines around consumer rights. Theorem will not warrant the safety and/or correct functioning of products where any original components have been changed or modified by non-Theorem approved and trained service & maintenance staff or external providers. Furthermore, safety is not guaranteed where components have been replaced with non-original Theorem approved parts. If any faults are detected upon receipt of this product please contact Theorem Power Lift Recliners. Any faults detected during normal use should be reported to Theorem immediately to determine if warranty conditions apply and, if so, the necessary repair or replacement work to be completed.

Please contact your Theorem stockist for further information.

THEOREM