



Fresh Coat Painters of Davenport, FL

POSITION DESCRIPTION

Position Title: Painter
Reports To: Operations Manager

Principle Function

Completes the painting scope of work in accordance with production standards established by the Painting a Contractors of America (PCA) and the Fresh Coat painting company.

Specific List of Responsibilities

- Always maintains the company standard, while working as a team player and supporter of fellow painters and the operations manager.
- Planning and Staging
 - Arrive at the job site at the precise start time and report to the operations manager for work specific goals and instructions.
 - Respect customer boundaries and space.
 - Assist in setting up a neat and organized area for our equipment, tools, and products.
 - Know your production goal for the day and monitor progress to ensure that goal is met or exceeded.
 - Pre-plan for next day

- Protection and Preparing
 - Use plastic, drop cloths, and tape to protect the surfaces of the home or project that is not to be painted.
 - Ensure expert preparation by sanding, scraping, and priming as appropriate to ensure proper adhesion.
- Application of Coatings
 - Completely cover painted surfaces to provide a smooth, opaque surface of uniform finish, color, appearance, and coverage.
 - Take steps to avoid cloudiness, spotting, holidays, laps, brush marks, runs, sags, ropiness, or other surface imperfections.
- Communication and Cleanup
 - Organize the worksite to minimally disturb our client's home.
 - Listen to and address any client concerns promptly and thoroughly.
 - At the end of each workday, remove empty cans, rags, rubbish, and other discarded paint materials from the site.
 - Upon job completion, clean glass and paint-spattered surfaces. Remove spattered paint by washing and scraping. Be careful not to scratch or damage adjacent finished surfaces.
- Basic personal responsibilities:
 - Maintain professional appearance: Hair combed, clean & neat, and wearing clean painter whites with no more than 10 percent of fabric covered in paint.
 - Be on time for all jobs.
 - Continue to learn and grow as a painter
 - Always establish and maintain good will with clients and prospective clients.
- Other duties and responsibilities requested by Fresh Coat leaders.