

Site
 HTC Handforth Dean
 Centre Management Suite
 Kiln Cross Lane
 Handforth
 Wilmslow
 Cheshire
 SK9 3PA

Date of Work
 29/10/2021 (completed)

WASH/INSPECT Trolley (A) 216422

Arrived	Done	On Site Time
26/10/2021 05:54	29/10/2021 16:02	10:08

Site Details

Site No.	HT0002
Customer Ref.	
Verisae Ref.	
Sales Order Number	
SAP By Design Contract	
Auto generate SAP invoice	
Have you read and understood the customer health and safety rules and processes? If not, you must not carry out any works.	Yes
Do you agree to abide by these processes whilst on site?	Yes

Job Details

Description of works	WASH/INSPECT Trolley (A)
Special instructions	There are no assets defined for this work order.

Permit to Work

Have you Logged On and Off Verisae/ATAS?	N/A
Permit to Work Received?	Y
If NO Please Comment Below	

Details

Repairs on Arrival	282
MF Repair	122
SS Repair	138
Wheelchair Repair	0
Specialist Repair	22
Dot com Repair	0
Funcart Repair	0
Ladder Repair	0
Luggage Trolley Repair (Airport)	0
Kiddo Repair (Airport)	0
Porter Trolley Repair (Airport)	0
Total Repaired	282
Awaiting Parts	0
Total for Collection	2
Trolleys Washed	1889
Inspect Retention System	N/A
All Exits Working	N/A
Requested Stock and Merchandise Trolleys	Yes
Stock/Merchandise Trolleys done	Yes
Ads Removed	N/A
Qty Ads Removed	0
Total Kiddo trolleys Inspected (Airport)	0
Total Porter Trolleys Inspected (Airport)	0
Total Units Inspected	1889


Parts

Stock

Outcome

Outcome	Complete
Completion comments	Inspection complete, All repairs have been completed and returned to service. Parts used as follows, castors x374 lap straps x53 infill x1 seat x2 handles x13

Signatures



Name
Carl Taylor

Date
29/Oct/2021 15:52

Name
Scott Hazlehurst

Date
29/Oct/2021 15:57