




THERMALLY BROKEN EXISTING WALL ANCHOR (EWA)



3D VIEW – BACK




3D VIEW – FRONT




PLAN – FIELD INSTALL




THERMALLY BROKEN EXISTING WALL ANCHOR – CUSTOM (EWA-C)



3D VIEW – BACK




3D VIEW – FRONT




PLAN – FIELD INSTALL




THERMALLY BROKEN STRAP (STRAP)



3D VIEW – BACK




3D VIEW – FRONT




PLAN – FIELD INSTALL




THERMALLY BROKEN REVERSE BASE ANCHOR



3D VIEW – BACK



3D VIEW – FRONT



ELEVATION – FIELD INSTALL

