

Report Date: 12/23/2021 9:29 AM  
 Test: 3 Point Bend Test  
 Batch: Unnamed


Specimen details

Specimen ID	Date	Time	Type	Width
Clear400Crack_1_12232021_092900	12/23/2021	9:29 AM	3 pt. Bend	6.000in

Specimen ID	Depth	Span Length
Clear400Crack_1_12232021_092900	0.250in	9.842in

Test Results

	MaxLoad	MaxStress
Unit	lbs	PSI
Lower limit	0.000	0.000
Upper limit	0.000	0.000
	127.524	5020.378



Report Date: 12/23/2021 9:31 AM  
 Test: 3 Point Bend Test  
 Batch: Unnamed


Specimen details

Specimen ID	Date	Time	Type	Width
Clear400Crack_2_12232021_093055	12/23/2021	9:30 AM	3 pt. Bend	6.000in

Specimen ID	Depth	Span Length
Clear400Crack_2_12232021_093055	0.250in	9.842in

Test Results

	MaxLoad	MaxStress
Unit	lbs	PSI
Lower limit	0.000	0.000
Upper limit	0.000	0.000
	126.044	4962.110



Report Date: 12/23/2021 9:33 AM  
 Test: 3 Point Bend Test  
 Batch: Unnamed

Specimen details

Specimen ID	Date	Time	Type	Width
Clear400Crack_3_12232021_093242	12/23/2021	9:32 AM	3 pt. Bend	6.000in

Specimen ID	Depth	Span Length
Clear400Crack_3_12232021_093242	0.250in	9.842in

Test Results

	MaxLoad	MaxStress
Unit	lbs	PSI
Lower limit	0.000	0.000
Upper limit	0.000	0.000
	106.907	4208.713

