

PROPELLER LOGBOOK

PROPELLER MODEL PHC-C39F-1RF/F8068

PROPELLER S/N <u>EE6464B</u>

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.



PROPELLER MAINTENANCE RECORD

. 4		١
1	- 27	
1	-4	


Position	PITCH RANGE
Propeller Model	High/Feather
Propeller S/N	Start Lock
Blade Design	Low
Blade S/N's	Reverse
No. 1	
No. 2	Aircraft Manufacturer
No. 3	Aircraft Model
No. 4	S/N_D-9034
No. 5	Registration <u>N2383A</u>
No. 6	•
Spinner Assembly Part No	

Date	Prop TSN	J A AIR CENTER DuPage Airport/WestChicago, IL. 60185 P 1 Repair Station #NF2R029L PROPELLER LOG #1	/es, ctions.	
		Type BEECHCRAFT V35A TT -0- N # 2383A TSMOH		
		S/N D-9034 REC. HR. METER 3526 PROPELLER MODEL PHC-C3YF-1RF/F8068 PROPELLER S/N EE6464B		
		PROPELLER INSTALLATION- INSTALLED THIS FACTORY NEW PHC-C3YF-1RF/F8068 S/N EE6464B ON BEECHCRAFT V35A S/N D-9034 ENGINE MODEL IO-520-BA S/N 241610-R AS PER D'SHANNON PRODUCTS STC SA01561CH.		
		REMOVED MCCAULEY PROPELLER MODEL 2A36C23-DP_G S/N 691388 WITH 3526.83 HOURS TOTAL TIME. SEE THE AIRFRAME ENTERY FOR DETAILS AND CHANGES TO THE WEIGHT AND BALANCE. THE AIRCRAFT, ENGINE, APPLIANCE, OR COMPONENT IDENTIFIED WAS		
		REPAIRED & INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER W.O. # 16881 DATE: OCTOBER 31, 2008		
		SIGNED: BRUCE P. REBE CHINI J.A. AIR CENTER, DUPAGE AIRPORT, W. CHICAGO, IL 60185 F.A.A. APPROVED REPAIR STATION #NF2R029		
			0	

determined to be in an airwor All routine maintenance com This Aircraft, Airframe, Ai	FL 32035 seechcraft Model: V35A SN# D-9034 PropTT: 6.51 PropTSMO: 6.51 s been inspected in accordance with a Beech Bonanza thy condition. All work accomplished is on file under	w/O # 7195 at Island Aviation, Inc. paired and inspected in d is approved for return to
determined to be in an airworthy All routine maintenance comple This Aircraft, Airframe, Aircr accordance with current regul	chcraft Model: V35A SN# D-9034 PropTT: 61.24 PropTSMO: 61.24 een inspected in accordance with a Beech Bonanza Ann condition. All work accomplished is on file under W/O) # 7486 at Island Aviation, Inc.

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspection	
	ISLAND AT FERNAND Date: 3/17/1 HOBBS/TA I certify that to determined to All routine ma This Aircraft	INA BEA II Ma ACH: 365 his Propell be in an a aintenance c, Airfram vith/currer 19886391	ke: Beechcraft Model: V35A SN# D-9034 N# 2383A 8.5 PropTT: 61.24 W/O 7784 er has been inspected in accordance with a Beech Bonanza Annual Inspection and was inworthy condition. All work accomplished is on file under W/O # 7785 at Island Aviation. Inc completed. e. Aircraft Engine, or Appliance identified herein was repaired and inspected in at regulations of the Federal Aviation Administration and is approved for return to).
				1
	Date: 4/0 HOBBS/ I certify the Annual In 8046 at Is This Airce accordance service. Ac Signature I SLAND FERNA Date: 06 HOBBS I certify the Annual In 8529 at Is This Airce accordance	MDINA B. 4/12 If TACH: 37 at this Prop espection a land Aviati raft, Airfra ee with cur AVIATI NDINA E 6/01/2013 /TACH: 3 hat this Pro espection a land Aviati raft, Airfra ext this Pro espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati raft, Airfra ext the cur espection a land Aviati	Alake: Beechcraft Model: V35A SN#D-9034 N# 2383A 12.4 PROPTT:115.14 W/O 8045 eller has been inspected in accordance with an Beechcraft Bonanza Maintenance Manual and was determined to be in an airworthy condition. All work accomplished is on file under W/O # on. Inc. All routine maintenance completed. Image: Aircraft Engine, or Appliance identified herein was repaired and inspected in rent regulations of the Federal Aviation Administration and is approved for return to 13 IA Date: 4/04/12 Date: 4/04/12 Propeller EACH, FL 32035 Make: Beechcraft Model: V35A SN#D-9034 N#2383A Make: Beechcraft Model: V35A SN#D-9034 N#2383A peller has been inspected in accordance with a Beechcraft Bonanza Maintenance Manual and was determined to be in an airworthy condition. All work accomplished is on file under W/O # on, Inc. All routine maintenance completed. Tent regulations of the Federal Aviation Administration and is approved for return to ame, Aircraft Engine, or Appliance identified herein was repaired and inspected in the return to a proved for return to a proved for return to the regulations of the Federal Aviation Administration and is approved for return to the regulations of the Federal Aviation Administration and is approved for return to the regulations of the Federal Aviation Administration and is approved for return to the regulations of the Federal Aviation Administration and is approved for return to the regulations of the Federal Aviation Administration and is approved for return to the regulations of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Administration and is approved for return to the results of the Federal Aviation Ad	

Date	Date: 07/02 HOBBS/TA I certify that Annual Insp 8836 at Islan This Aircraf accordance service. A&I Signature:	DINA BEACH, FL. 2/2014 Make ACH: 3810.54 this Propeller has been ection and was determed Aviation, Inc. All roft, Airframe, Aircraft with current regulation 1988639 IA	ce: Beechcraft	ppleted. e identified herein iation Administrat	ft Bonanza Maint	l inspected in	
	the same of the sa	PENEFIELD AVIATION PROPELLER LOG DATE: 9-4-15					
	A/C N#	MAKE	MODEL	A/C S/N	нм	тѕрон	
	2383A	Beech	V35A	D-9034	3870.6	344.6	
	prop and rota This aircraft has	ted 180 degree an	d reinstalled using	a new o-ring.		blades. Removed ein. 353483286 IA	•



December 11, 2018 Tach 3984.49 N2383A	
Dressed blades and serviced hub with Aeroshell #6 grease. I certify this propeller has been inspe accordance with an annual inspection and was determined to be in airworthy condition.	rectives, cted in nspections.
Alan Shackleton 2710518 A&P/IA	
March 22, 2020 Tach 3997.38 N2383A	
Checked blades and serviced hub with Aeroshell #6 grease. I certify this propeller has been inspect accordance with an annual inspection and was determined to be in airworthy condition.	ed in
Alan Shackleton 2710518 A&P / IA	1 A 1 A
March 15, 2022 Tach 3997.38 N2383A	
Checked blades and serviced hub with Aeroshell #6 grease. I certify this propeller has been inspectationate with an annual inspection and was determined to be in airworthy condition.	eted in
Alan Shackleton 2710518 A&P / IA	. 10 -
June 1, 2023 Tach 4026.72 N2383A	
Checked blades and serviced hub with Aeroshell #6 grease. I certify this propeller has been inspe accordance with an annual inspection and was determined to be in airworthy condition.	cted in
Alan Shackleton 2710518 A&P/IA	
January 11, 2025 Tach 4039.45 N2383A Checked blades and serviced hub with Aeroshell #6 grease. I certify this propeller has been inspected with an annual inspection and was determined to be in airworthy condition.	ed in
Checked blades and serviced hub with Aeroshell #6 grease. I certify this proposition. accordance with an annual inspection and was determined to be in airworthy condition.	2× = -
Alan Shackleton 2710518 A&P / IA	
2/10316 Act / 22	
2/10516 Act / 21	
2/10516 ACC / 2/	
2/10516 ACC / 2/	
Z/10516 ACC / Z/	