Water System Name: Priest Lake Water		PWS ID No.: 1090229 RE
Collector: Dion Holton	Date Collected: 09/28/2026	County:
Report Results to: Priest Lake Water Lisa Claar 279 Tracy Lane Priest River, ID 83856		
Phone: (986) 205-8844	Fax:	
E-Mail: plwaterllc@gmail.com,pwsreports@deq.idaho.gov,dholton@idrwa.org		

COLIFORM BACTERIA
ANALYSIS REPORT
CONTAMINANT ID# 3100

Type of System:	**Public**
Type of Sample:	**Compliance Sample**
Lab Order No.:	**2026090775**

Water system info must be fully filled out or samples will not be run. Private samples do not need PWS# or Chlorine residual. Your sample will be analyzed for TOTAL COLIFORMS unless you specify analysis under Remarks.

Laboratory Name:
Accurate Testing Labs, LLC
7950 Meadowlark Way
Coeur d'Alene, ID 83815
Phone (208) 762 8378 Fax (208) 762 9082
Web site: www.accuratetesting.com
E-mail: info@accuratetesting.com

Lab EPA ID No: ID00912

For PWS only, if this is a repeat sample, mark the date of the ORIGINAL POSITIVE SAMPLE.

Sample Number	Sample Type	Sample Location	Time Collected	Chlorine Residual ppm	Original Sample Date	Total Coliform Method: SM9223B-PA	E. Coli Method: SM9223B-PA
304991	RT	Block 4 Lot 9	09:15	0		Absent	Absent

Sample Transportation by (Name):	Dion Holton	Date/Time:	09/28/2026 10:44	Analyst: LN	Date Analyzed: 09/29/2026
Sample Received by (Name):	JM	Date/Time:	09/28/2026 10:44	Supervisor: Rhena Cooper	
Remarks:				Date Reviewed and Printed: 09/29/26	