Defect Check Report

Vehicle Reg/Trailer ID: [removed]
Driver: Anonymised - report 1
Date/Time: 13/11/2026 08:31:09 - 13/11/2026 08:34:54

Defect Area	Duration	State	Note
I am Fit to Drive	08:31:10 - 08:31:13	No defect	No note
I hold a valid licence for this category of vehicle	08:31:18 - 08:31:19	No defect	Yes
I have checked my Route for Weight Restrictions	08:31:23 - 08:31:25	No defect	No note
Vehicle Height Marker	08:31:30 - 08:31:53	No defect	12' 2"
Photo of Dashboard	08:31:57 - 08:32:58	No defect	No note
Wipers	08:33:01 - 08:33:01	No defect	No note
Lights	08:33:03 - 08:33:03	No defect	No note
Excessive Engine Exhaust Smoke	08:33:04 - 08:33:05	No defect	No note
Security of body/wings	08:33:06 - 08:33:07	No defect	No note
Tyres & Wheel Fixings	08:33:10 - 08:33:14	No defect	OK
Washers	08:33:15 - 08:33:26	No defect	frozen
Fuel /Oil Leaks	08:33:29 - 08:33:30	No defect	No note
Brakes	08:33:32 - 08:33:33	No defect	No note
Mirrors inc V &VI	08:33:34 - 08:33:35	No defect	No note
Camera/Monitor	08:33:36 - 08:33:37	No defect	No note

Defect Check Report

Defect Area	Duration	State	Note
Glass/ View to Front	08:33:41 - 08:33:41	No defect	No note
Seat Belts	08:33:42 - 08:33:43	No defect	No note
Steering	08:33:44 - 08:33:45	No defect	No note
Indicators	08:33:46 - 08:33:47	No defect	No note
Prominent Warning Signs	08:33:48 - 08:33:59	No defect	ok
Reflectors	08:34:02 - 08:34:03	No defect	No note
Battery Security (condition)	08:34:05 - 08:34:05	No defect	No note
Grease Nipples Greased	08:34:07 - 08:34:08	No defect	Yes
Horn	08:34:10 - 08:34:11	No defect	No note
Ad Blu Neck Present?	08:34:13 - 08:34:22	No defect	ok
Wheels Torqued	08:34:24 - 08:34:24	No defect	No note
Hydraulic oil level	08:34:26 - 08:34:27	No defect	No note
Auxiliary engine oil	08:34:28 - 08:34:29	No defect	No note
Auxiliary coolant level	08:34:30 - 08:34:30	No defect	No note
Auxiliary engine radiator not obstructed	08:34:33 - 08:34:34	No defect	No note
Filter state indicator-service air filter if red	08:34:36 - 08:34:36	No defect	No note
Mesh screens in body are clean & fitted correctly	08:34:38 - 08:34:39	No defect	No note

Defect Check Report

Defect Area	Duration	State	Note
Centre baffle is in position duals only	08:34:40 - 08:34:41	No defect	No note
Mechanical damage to brush gear	08:34:43 - 08:34:43	No defect	No note
Brushes for adjustment & wear	08:34:47 - 08:34:48	No defect	No note
Spray jets for correct operation-clean if necessary	08:34:50 - 08:34:50	No defect	No note