## **Tweed Laboratory Centre**



Page 1 of 2

### FINAL CERTIFICATE OF ANALYSIS

Client: Broken Head Quarry

Address: PO Box 165

BYRON BAY NSW 2481

Lims1 Report No: 240048 / 00

Attention: Leonie Rowe Client Reference:

Copy To: Date of Report: 16/01/2024

All pages of this report have been checked and approved. This document may not be reproduced except in full.

Results apply to the sample(s) as submitted to the laboratory.

Taken By: Client No of Samples: 4

 Date Taken:
 03/01/2024
 Date Testing Commenced:
 03/01/2024

 Date Received:
 03/01/2024
 Date Testing Completed:
 11/01/2024

CHEMICAL REPORT Job Description: Quarry - Air Monitoring PO8346

LIMS No.	Sample/Site Identification	Sample/Site Description	Sample Matrix
240048-1	SPD1	1	Other
240048-2	SPD2	2	Other
240048-3	SPD3	3	Other
240048-4	SPD4	4	Other



Page 2 of 2



# **Tweed Laboratory Centre**

Client: Broken Head Quarry

240048 Lims1 Report No: **Date Testing Completed:** Address: PO Box 165 11/01/2024 16/01/2024

Date of Report:

**BYRON BAY** NSW 2481

Attention: Leonie Rowe

CHEMICAL **REPORT Job Description:** Quarry - Air Monitoring PO8346

### REPORT COMMENTS

Additional information relevant to this report can be found in the Sample Receipt Notice and Chain of Custody. Measurement Uncertainty available upon request.

LOR = Limit of reporting Key:

= NATA accreditation does not cover the performance of

this service

Value is considered an estimate

NP Not present = Less than = Greater than

### **ANALYSIS RESULTS**

Sample Identification:			SPD1	SPD2	SPD3	SPD4
Date Taken:			03/01/2024	03/01/2024	03/01/2024	03/01/2024
			12:00 AM	12:00 AM	12:00 AM	12:00 AM
Test	Method	Units	240048-1	240048-2	240048-3	240048-4
^Air Monitoring	P13	g/m2/mth	0.2	0.2	0.2	0.2
^Ash Content	P13	g/m2/mth	0.2	0.2	0.2	0.2