



Chute Demolition & Refurbishment




BX-543 Receipt




BX-543 01 Evidence of minimal tile adhesive used



BX-543 02 Rust evident



BX-543 05 LHS Rust & moisture evident



BX-543 07 Removal of tiles in pipe stub



BX-543 10 Rust evident



BX-543 13 Back wall blasted




BX-543 21 RHS wall, marking out tiles ready for installation



BX-543 25 Notch trowelled adhesive application & tiles fully bedded in



BX-543 26 Installation of floor & wall tiles



BX-543 39 Ready for despatch



BX-543 Despatched