



CTL Reservoir - Batch Maintenance clean



Industrial Tank Cleaning Case Study

Client: Enovate Group

Lead Contact: Mike

This was a specialised industrial cleaning project involving a 10KL stainless batch tank contaminated with solidified oil and toner powder residue. Using ultra-high-pressure hydro-lancing techniques, the hardened material and sludge were effectively broken down and removed. Waste material was continuously collected via an open IBC positioned beneath the tank's bottom valve, ensuring efficient containment and disposal throughout the operation.



Contact



Chris Brooks - 0408 004 123



chris@aquaprep.com.au



www.aquaprep.com.au

